

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

NOV 10 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1631936319

OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: JR'S HORZ FEDERAL #001	Facility Type: SWD

Surface Owner: Federal	Mineral Owner:	API No. 30-015-33066
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	10	26S	29E	380'	North	330'	West	Eddy

Latitude 32.0632515 Longitude -103.9792099

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 625 bbls PW	Volume Recovered: 624 bbls PW
Source of Release: Alarm Malfunction	Date and Hour of Occurrence: 11/6/2016 unknown	Date and Hour of Discovery: 11/6/2016 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson - NMOCD / Shelly Tucker - BLM	
By Whom? Dakota Neel	Date and Hour: 11/8/2016 10:02 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when an alarm malfunctioned due to loss of electricity causing the tank to overflow. Vacuum trucks were immediately dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within a falcon lined facility. Vacuum trucks were dispatched to recover all standing fluids. The liner and equipment were pressure washed. Concho will have the spill site inspected to determine if any possible contamination occurred from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<p>Signature: <i>Dakota Neel</i></p> <p>Printed Name: Dakota Neel</p> <p>Title: Environmental Coordinator</p> <p>E-mail Address: dneel2@concho.com</p> <p>Date: 11/11/2016 Phone: 575-748-6933</p>	<p>OIL CONSERVATION DIVISION</p> <p>Approved by Environmental Specialist: <i>[Signature]</i></p> <p>Approval Date: <i>11/14/16</i> Expiration Date: <i>N/A</i></p> <p>Conditions of Approval: Attached <input checked="" type="checkbox"/></p>
---	---

* Attach Additional Sheets If Necessary

2RP-3987

Patterson, Heather, EMNRD

From: Dakota Neel <DNeel2@concho.com>
Sent: Friday, November 11, 2016 11:43 AM
To: stucker@blm.gov; Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: James_Amos@blm.gov; Robert McNeill; Rebecca Haskell
Subject: (C-141 Initial) JRs Horz Federal #1 SWD (TB) Initial (30-015-33066)
Attachments: 11-6-2016 JRs Horz Federal #1 SWD (TB) Initial.pdf


Mr. Bratcher/Ms. Tucker,

Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Dakota Neel
HSE Coordinator
COG Operating LLC
Cell: 432-215-2783
dneel2@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Dakota Neel <DNeel2@concho.com>
Sent: Tuesday, November 08, 2016 10:02 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; stucker@blm.gov
Cc: Robert McNeill; James_Amos@blm.gov
Subject: (Notification) JR'S HORZ FEDERAL #001 (30-015-33066)

Ms. Patterson/Ms. Tucker,

COG Operating LLC is reporting a release on the JR'S HORZ FEDERAL #001 (30-015-33066)

Unit D Section 10 Township 26S Range 29E 380 FNL 330 FWL
The release occurred at approximately 11:00 am on 11-06-2016
Estimated Released: Approx. 961 bbls of PW.
Estimated Recovered: Approx. 960 bbls of PW.

This release occurred within a falcon lined facility and vacuum trucks were dispatched to remove all standing fluid from within the liner. This release was caused by an alarm malfunction. The area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Dakota Neel
HSE Coordinator
COG Operating LLC
Cell: 432-215-2783
dneel2@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.