

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

APR 03 2017

Form C-14
Revised August 8, 20

Submit 1 Copy to appropriate District Office
RECEIVED accordance with 19.15.29 NMA

FAB1710030889 **Release Notification and Corrective Action**
NAB1710037153 **OPERATOR** Initial Report Final Report

| | |
|--|--|
| Name of Company DCP <i>316785</i> | Contact Haskell Conder |
| Address 10 Desta Drive, Suite 400 West | Telephone No. cell 432-557-1127 |
| Facility Name O-4 Ext Line Leak | Facility Type Natural Gas Gathering Pipeline |
| Surface Owner BLM | Mineral Owner |
| API No. | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|-----------|--------------|-----------|---------------|------------------|---------------|----------------|-------------|
| Unit Letter | Section 8 | Township 18S | Range 31E | Feet from the | North/South Line | Feet from the | East/West Line | County Eddy |
|-------------|-----------|--------------|-----------|---------------|------------------|---------------|----------------|-------------|

Latitude: 32.76300 **Longitude :** -103.89300

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release: Natural Gas | Volume of Release 347 MCF | Volume Recovered 0 |
| Source of Release Pipeline | Date and Hour of Occurrence 11:13 03/23/17 | Date and Hour of Discovery 11:13 03/23/17 |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* N / A | | |
| Describe Cause of Problem and Remedial Action Taken.* DCPM discovered a small pin hole leak above ground on the O-4 line. DCPM field operations and Field maintenance shut in gas and repaired pipeline. | | |
| Describe Area Affected and Cleanup Action Taken.* Reporting this event due to the 50 MCF requirements. DCPM field operations and Field maintenance shut in gas and repaired pipeline. The leak was assessed and no liquids were present. This was a dry leak. The line was repaired and put back in service at 16:30. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <i>Haskell Conder</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Haskell Conder | Approved by Environmental Specialist <i>[Signature]</i> | |
| Title: Compliance Coordinator | Approval Date: 4/4/17 | Expiration Date: NIA |
| E-mail Address: hconder@dcpmidstream.com | Conditions of Approval: FINAL | Attached <input type="checkbox"/> |
| Date: 03/24/17 Phone: 432-557-1127 | | |

* Attach Additional Sheets If Necessary

2RP-4163

Bratcher, Mike, EMNRD

From: Blair, Yvonne B. <YBBlair@dcpmidstream.com>
Sent: Monday, April 3, 2017 1:12 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc: Conder, Haskell P
Subject: O-4 EXT Line C141.doc
Attachments: O-4 EXT Line C141.doc

Mike

Please see the attached C141 for release on DCP O-4 Ext.

Yvonne Blair
Compliance Coordinator
DCP Midstream
575-361-2406