

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Artesia District II
Received
4/19/17
Form C-141
Revised April 3, 2017
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1711041252

Name of Company OXY USA INC <i>1100910</i>		Contact CASEY L SUMMER	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address PO BOX 4294; HOUSTON, TX 77210		Telephone No. 575-513-8289		
Facility Name BANK 18 FEDERAL COM #1H		Facility Type OIL WELL		
Surface Owner BLM	Mineral Owner BLM	API No. 30-015-41447		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	18	23S	29E	133	NORTH	485	WEST	EDDY

Latitude 32.3124352 Longitude -104.0305023 NAD83

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 120 bbls	Volume Recovered 120 bbls
Source of Release 3 inch steel line	Date and Hour of Occurrence 4-14-2017	Date and Hour of Discovery 4-14-2017
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker-BLM; Olivia Yu-NMOCD; Mike Bratcher-NMOCD; Crystal Weaver-NMOCD	
By Whom? Casey Summers	Date and Hour 4-14-2017 9:32 pm	*E-mail 4/17/17 @ 9:43am
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This leak was caused by a 3-inch steel line from the heater treater water leg to the inlet for water tanks failing. Inlet to water tank has been repaired. All fluid was contained within above ground Falcon lined containment.

Describe Area Affected and Cleanup Action Taken.*

All fluid was recovered via vacuum truck from Falcon lined containment. Pictures have been included of cleaned containment. C141 has been marked as Initial and Final since all fluids were recovered.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: CASEY L SUMMERS	Approved by Environmental Specialist: <i>Crystal Weaver</i>	
Title: ENVIRONMENTAL ADVISOR	Approval Date: <i>4/20/17</i>	Expiration Date: <i>N/A</i>
E-mail Address: casey.summers@oxy.com	Conditions of Approval: SEE BELOW	Attached <input type="checkbox"/>
Date: 4-19-17 Phone: 575-513-8289		

COA: It is OCD's understanding that all impacted material has been removed/replaced, the liner cleaned and inspected for integrity.

2RP-4177

* Attach Additional Sheets If Necessary



Weaver, Crystal, EMNRD

From: Casey_Summers@oxy.com
Sent: Wednesday, April 19, 2017 12:33 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; stucker@blm.gov; Jennifer_Hudgens@oxy.com
Cc: cbrunson@bbcinternational.com; kswinney@bbcinternational.com; kathy@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Bank 18 Fed Com 1H: Initial & Final C141
Attachments: BANK 18 FED COM 1H - INITIAL & Final C141.pdf

All,
Please find the Initial & Final C141 attached for the released referred to below.

Casey Summers
O: (575)-628-4152
C: (575)-513-8289

-----Original Message-----

From: Summers, Casey L
Sent: Monday, April 17, 2017 9:43 AM
To: 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'Weaver, Crystal, EMNRD' <Crystal.Weaver@state.nm.us>; 'Tucker, Shelly' <stucker@blm.gov>; Hudgens, Jennifer A <Jennifer_Hudgens@oxy.com>
Cc: 'Cliff Brunson' <cbrunson@bbcinternational.com>; 'Ken Swinney' <kswinney@bbcinternational.com>; 'Kathy Purvis' <kathy@bbcinternational.com>; 'Jennifer Gilkey' <jgilkey@bbcinternational.com>
Subject: Bank 18 Fed Com 1H

All,
This is to inform you that Oxy Permian had a release at the Bank 18 Fed Com 1H on 4/14/2017.
-Release Location: Legal D-18-23S-29E, API: 30-015-41447 -Release Volume: 0 bbls of Oil and 120 bbls of Produced Water (released was all within the above ground Falcon Lined Containment)
-Recovered: 120 bbls recovered
-Cause of Release: 3 INCH STEEL LINE FROM HEATER TREATER WATER LEG TO INLET FOR WATER TANKS FAILED
-Approximate Area impacted by release: All within containment
-GPS Coordinates and Driving Direction: 32.3124352,-104.0305023, FROM CARLSBAD ON LOVING HWY, TURN LEFT ON 31, GO 4 MILES AND TURN RIGHT ON US REFINERY ROAD, GO .25 MILE TO LOCATION

Mike,
I apologize I sent the below to district 1 on Friday. If you are good with it I will send initial and final C141 on this?

Please let me know if you have any questions.

Casey Summers
O: (575)-628-4152
C: (575)-513-8289

-----Original Message-----
From: Summers, Casey L

Sent: Friday, April 14, 2017 9:32 PM

To: Yu, Olivia, Emnrd <Olivia.yu@state.nm.us>; stucker@blm.gov

Subject: Bank 18 Fed Com 1H

Olivia and Shelly,

Oxy had a 120 barrel release at the Bank 18 Fed Com 1H today (API: 30-015-41447). The release occurred inside an above ground Falcon line containment and it was recovered. I want to make both of you aware of it before the weekend. I will send an official initial notification to you on Monday when I have more details.

Thanks,

Casey Summers

Weaver, Crystal, EMNRD

From: Casey_Summers@oxy.com
Sent: Monday, April 17, 2017 9:43 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; stucker@blm.gov; Jennifer_Hudgens@oxy.com
Cc: cbrunson@bbcinternational.com; kswinney@bbcinternational.com; kathy@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Bank 18 Fed Com 1H

All,
This is to inform you that Oxy Permian had a release at the Bank 18 Fed Com 1H on 4/14/2017.
-Release Location: Legal D-18-23S-29E, API: 30-015-41447 -Release Volume: 0 bbls of Oil and 120 bbls of Produced Water (released was all within the above ground Falcon Lined Containment)
-Recovered: 120 bbls recovered
-Cause of Release: 3 INCH STEEL LINE FROM HEATER TREATER WATER LEG TO INLET FOR WATER TANKS FAILED
-Approximate Area impacted by release: All within containment
-GPS Coordinates and Driving Direction: 32.3124352,-104.0305023, FROM CARLSBAD ON LOVING HWY, TURN LEFT ON 31, GO 4 MILES AND TURN RIGHT ON US REFINERY ROAD, GO .25 MILE TO LOCATION

Mike,
I apologize I sent the below to district 1 on Friday. If you are good with it I will send initial and final C141 on this?

Please let me know if you have any questions.

Casey Summers
O: (575)-628-4152
C: (575)-513-8289

-----Original Message-----

From: Summers, Casey L
Sent: Friday, April 14, 2017 9:32 PM
To: Yu, Olivia, Emnrd <Olivia.yu@state.nm.us>; stucker@blm.gov
Subject: Bank 18 Fed Com 1H

Olivia and Shelly,
Oxy had a 120 barrel release at the Bank 18 Fed Com 1H today (API: 30-015-41447). The release occurred inside an above ground Falcon line containment and it was recovered. I want to make both of you aware of it before the weekend. I will send an official initial notification to you on Monday when I have more details.

Thanks,
Casey Summers