

District I
1625 N. French Dr., Hobbs
District II
811 S. First
District III
1000 R
District IV
1220 S. S
Please refer to the New Mexico Oil
Conservation Division Website for
updated form(s) at:
[http://www.emnrd.state.nm.us/
OCD/forms.html](http://www.emnrd.state.nm.us/OCD/forms.html)
Thank you

State of New Mexico
Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 23 2018

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: XTO Energy 5380	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-221-7331
Facility Name: Goldenchild CTB	Facility Type: Exploration and Production
Surface Owner: State	Mineral Owner: State
API No. 30-01541846	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	6	25S	29E	800	South	330	East	Eddy

Latitude 32.154435 Longitude -104.016846

NATURE OF RELEASE

Type of Release Oil and produced water *	Volume of Release 77 bbl 30 bbl Oil / 47 bbl RW	Volume Recovered 4 bbl 28 bbl Oil / 40 bbl RW
Source of Release Gun barrel	Date and Hour of Occurrence 2/10/2018, time unknown	Date and Hour of Discovery 2/11/2018, 7:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Crystal Weaver (ENMRD), Kenda Montoya (SLO)	
By Whom? Jacob Foust	Date and Hour 2/11/2018, 3:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Gun barrel overflowed, possibly due to plug in dump line. Line had cleared by the time lease operator discovered release and was flowing normally again.		
Describe Area Affected and Cleanup Action Taken.* Most fluid was captured within impermeable lined containment, with some overspray impacting east, west, and north ends of containment. Vacuum truck was dispatched, 70bbl was recovered from lined containment, and 4bbl overspray recovered from caliche pad. An environmental contractor was retained to assist with the remediation and soil samples have been collected.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 2/26/18	Expiration Date: N/A
E-mail Address: Kyle_Littrell@xtoenergy.com	Conditions of Approval: see attached	
Date: 2/23/2018 Phone: 432-221-7331	Attached <input checked="" type="checkbox"/> 2018-4635	

* Attach Additional Sheets If Necessary

2/26/18 AB

Operator/Responsible Party,

The OCD has received the form C-141 you provided on **2/23/18** regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number 2RP-40310 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District II office in Artesia on or before 3/23/18. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief

1220 South St. Francis Drive

Santa Fe, New Mexico 87505

505-476-3465

jim.griswold@state.nm.us

Weaver, Crystal, EMNRD

From: Ruth, Amy <Amy_Ruth@xtoenergy.com>
Sent: Friday, February 23, 2018 10:40 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Honea, Tammy
Cc: Naranjo, Mark; Montoya, Kenda; Littrell, Kyle; Foust, Bryan; Sanders, Toady; McSpadden, Wes
Subject: Initial C-141 - Goldenchild Central Tank Battery 2-10-18
Attachments: Initial C-141 - Goldenchild CTB 2-10-18.pdf

Good Morning, Everyone,

Please find attached the initial C-141 detailing the accidental release at the referenced facility. Call or contact us anytime with questions or concerns and thank you for your help.

Respectfully,

Amy C. Ruth

Delaware Basin Division
Environmental Coordinator
3104 E. Greene Street | Carlsbad, NM 88220 | M: 432.661.0571 | O: 575.689.3380



This document may contain information that is privileged, confidential and exempt from disclosure under applicable law. If you are not the intended recipient, you are notified that any unauthorized disclosure, copying, distribution or action on/of the contents of this document is prohibited.

From: Montoya, Kenda [mailto:kmontoya@slo.state.nm.us]
Sent: Thursday, February 15, 2018 11:03 AM
To: Foust, Bryan
Cc: Naranjo, Mark
Subject: RE: Notification of release

Thank you for the notification Bryan. I have copied Mark Naranjo, Assistant Director of our Field Division, please also include him in any communication regarding the spill.

Thank you,

Kenda Montoya
Oil and Gas Lease Manager
Oil, Gas and Minerals Division
505.827.5749
New Mexico State Land Office
310 Old Santa Fe Trail
Santa Fe, NM 87501
or
P.O. Box 1148



Santa Fe, NM 87504-1148
kmontoya@slo.state.nm.us
nmstatelands.org



.....
CONFIDENTIALITY NOTICE - This e-mail transmission, including all documents, files, or previous e-mail messages attached hereto, may contain confidential and/or legally privileged information. If you are not the intended recipient, or a person responsible for delivering it to the intended recipient, you are hereby notified that you must not read this transmission and that any disclosure, copying, printing, distribution, or use of any of the information contained in and/or attached to this transmission is STRICTLY PROHIBITED. If you have received this transmission in error, please immediately notify the sender and delete the original transmission and its attachments without reading or saving in any manner. Thank you.

From: Foust, Bryan [mailto:Bryan_Foust@xtoenergy.com]
Sent: Thursday, February 15, 2018 10:21 AM
To: Montoya, Kenda <kmontoya@slo.state.nm.us>
Subject: Notification of release

Good Morning Kenda, my name is Jacob Foust and I'm with XTO Energy. I'm writing to notify you of a release we had at our Goldenchild Central Tank Battery on Sunday morning. It was over 25 barrels, mostly oil. When I went to notify the appropriate agencies, I misread the map and thought the spill was on federal land. I notified the OCD and BLM. Today, upon closer inspection, I noticed it is in fact on state land. I apologize for the mistake and the late notification. We are working on the C141 now and will have it turned in before the deadline. Sorry again about the mix-up, it won't happen again. Thank you, please don't hesitate to contact me with any questions or concerns.

Bryan Jacob Foust
XTO Energy
EH&S Coordinator
432-266-2663

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Weaver, Crystal, EMNRD

From: Foust, Bryan <Bryan_Foust@xtoenergy.com>
Sent: Sunday, February 11, 2018 3:19 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; stucker@blm.gov; jamos@blm.gov
Cc: Littrell, Kyle; Ruth, Amy; Sanders, Toady
Subject: Notification of release at XTO - golden child central tank battery

Good afternoon. This morning we experienced a release in excess of 25 barrels at our Goldenchild central tank battery. Further details will be sent in with form c141 once we finish our investigation.

Thank you, please don't hesitate to call or email me with any questions.

Jake Foust
XTO Energy
(432)-266-2663

Weaver, Crystal, EMNRD

From: Foust, Bryan <Bryan_Foust@xtoenergy.com>
Sent: Sunday, February 11, 2018 3:19 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; stucker@blm.gov; jamos@blm.gov
Cc: Littrell, Kyle; Ruth, Amy; Sanders, Toady
Subject: Notification of release at XTO - golden child central tank battery

Good afternoon. This morning we experienced a release in excess of 25 barrels at our Goldenchild central tank battery. Further details will be sent in with form c141 once we finish our investigation.

Thank you, please don't hesitate to call or email me with any questions.

Jake Foust
XTO Energy
(432)-266-2663