


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Duke Energy Field Services	Contact: Mark Owens
Address: 1625 West Marland, Hobbs, NM 88240	Telephone No.: (505) 397-5541
Facility Name: G-28-14 Ext. 3	Facility Type: 6" Marlex Line
Surface Owner: Deep Wells Ranch	Mineral Owner: Federal
Lease No.:	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	26	23 S	36 E					Lea

141' **Latitude:** N 32° 16' 49.349" **Longitude:** W 103° 14' 27.415"

NATURE OF RELEASE

Type of Release: Natural Gas Pipeline Fluids	Volume of Release: 12 barrels	Volume Recovered: 10 barrels
Source of Release: 6" Marlex pipeline operating at 18-20 lbs with a normal daily flow rate of 20-30 mcf	Date and Hour of Occurrence: 27 March 2005	Date and Hour of Discovery: 27 March 2005
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink, NMOCD	
By Whom? Lynn Ward	Date and Hour: 27 March 2005 @1407 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* 6" Marlex line began leaking, due to a weld failure. A line clamp was installed and the section replaced.		
Describe Area Affected and Cleanup Action Taken.* The affected area consists of approximately 6,660 square feet of pasture land owned by Deep Wells Ranch. The section with the failed weld has been replaced.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Mark Owens	Approved by District Supervisor:	
Title: Construction Maintenance Supervisor	Approval Date:	Expiration Date:
E-mail Address: mrowens@duke-energy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Phone:	

* Attach Additional Sheets If Necessary

facility - pPAC0625525462
incident - nPAC0625526837
application - pPAC0625527032

RP # 1029