

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Occidental Permian Limited Partnership	Contact Steven M. Bishop
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (505) 397-8251
Facility Name North Hobbs Unit Injection Well #29-331 321	Facility Type Production

Surface Owner Occidental Permian Limited Partnership	Mineral Owner Occidental Permian Limited Partnership	Lease No.
---	---	-----------

LOCATION OF RELEASE

API# 30025074310000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
'G'	29	18-S	38-E					LEA

Latitude N32°43'10.20" Longitude 103°10'02.50"

NATURE OF RELEASE

Type of Release Injection Water	Volume of Release 22 bbls water	Volume Recovered 20 bbls water
Source of Release 2" steel riser valve on remote header on well NHU #29-321 location	Date and Hour of Occurrence 12/26/2004 08:00 AM	Date and Hour of Discovery 12/26/2004 08:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Robert Gilbert	Date and Hour 11/26/2004 08:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.* A 2" steel valve on a remote header froze and burst causing spill. The header is located on the location for North Hobbs Unit Well # 29-321. Replaced the damaged valve with a new one.

Describe Area Affected and Cleanup Action Taken.* Area affected approximately 25' X 50' to the north and west of the well location. All fluid escaped as a spray and gathered in a caliche lease road to the north and west of the location. Approximately 20 bbls was picked up via vacuum trucks from the lease road. The ground had been saturated by recent snow. Affected area will be remediated to NMOCD guidelines for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Steven M. Bishop		Approved by District Supervisor: <i>Chris Williams</i>	
Title: HES Technician		Approval Date: <i>5/21/07</i>	Expiration Date: <i>6/21/07</i>
E-mail Address: Steven_Bishop@oxy.com		Conditions of Approval: <i>Need final report.</i>	Attached <input type="checkbox"/>
Date: 12/27/2004	Phone: (505) 397-8251		

* Attach Additional Sheets If Necessary

*incident - n PAC0714448280
application - p PAC0714448350*

RPT# 1363