


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	Cameron Oil & Gas, Inc.	Contact	G. David Sweeney
Address	PO Box 1455, Roswell, NM88201	Telephone No.	505-420-1108 cell 627-3284 office
Facility Name	Flat C Sharp	Facility Type	Tank Battery

Surface Owner	S&D Partnership	Mineral Owner		Lease No.	5503
---------------	-----------------	---------------	--	-----------	------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	11	23S	37E	1980	North	660	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	oil & produced water	Volume of Release	155	Volume Recovered	130-25 burned
Source of Release	oil tank & water tank	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat with OCD District I		
By Whom?	G. David Sweeney	Date and Hour	10:30 a.m. on 07-30-07		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
See Form C-141 Attachment Item (A) **LIGHTNING STRUCK BTW 2 TANKS DESTROYED**

Describe Area Affected and Cleanup Action Taken.*
See Form C-141 Attachment Item (B)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>G. David Sweeney</i>	OIL CONSERVATION DIVISION	
Printed Name: G. David Sweeney	Approved by District Supervisor: <i>[Signature]</i>	
Title: Production Superintendent	Approval Date: 8.7.07	Expiration Date: _____
E-mail Address:	Conditions of Approval: _____	Attached <input type="checkbox"/> _____
Date: 7.31.07 Phone: 420-1108		

* Attach Additional Sheets If Necessary

RP# 7516

FORM C-141 ATTACHMENT

Cameron Oil & Gas, Inc.
Flat C Sharp: Unit Letter H, S11-T23S-R37E, Lea County, NM



Describe Cause of Problem and Remedial Action Taken.*

- (A) At approximately 1:00 p.m. on 07-29-07 lightning struck the tank battery causing an explosion. The Eunice Fire Department was dispatched and extinguished what small fire there was still burning. The oil tank had approximately 25 bbls. of oil and it was burned up in the explosion - no oil was released. The water tank burned to 1/3 of its size and the produced water and skim of oil was released in the dirt. It was all contained in the dike. A vacuum truck recovered approximately 130 bbls. of fluid from the dike (30bbls.) and the 1/3 of tank 100 bbls.

Describe Area Affected and Cleanup action Taken.*

- (B) The oil tank blew out of dike approximately 30' to the West. The bottom blew out approximately 30' to the East on location. The water tank melted down to 1/3 and all fluid was contained in the dike. A vacuum truck received 130 bbl. of water. A backhoe will remove all the dirt in the tank berm and it will be sent to J&L Landfarm. A new tank pad lined with plastic and a new berm will be constructed. A new 300 bbl. oil tank and 300 bbl. water tank will be placed on the new pad. There was no release of liquids outside of the tank berm. There was only a small amount of oil in the oil tank, we had sold our oil before the incident.