

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Mickey Garner
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU 0524-036	Facility Type Oil and Gas

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No 30-025-03058-00-00
------------------------------------------	------------------------------------------	------------------------------------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	5	18S	35E					Lea

Latitude **N 32.47.038** Longitude **W 103.28.843**

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 53bbl (21oil, 32water)	Volume Recovered (3oil, 5water)
Source of Release 3" Steel Flowline	Date and Hour of Occurrence 11-8-2007 0100	Date and Hour of Discovery 11-8-2007 1130
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Richards	
By Whom? Mickey Garner	Date and Hour 11-9-2007 0900	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
On Thursday November 8, 2007 at 1130 hrs a leak was discovered coming from a 3" steel flowline on EVGSAU #0524-036. Amount spilled was 21 bbls of oil and 32 bbls of produced water. The spill was not contained and affected approximately 8,000 sq/ft of pasture. The leak was found by a COPC employee. Upon arrival the MSO discovered that the leak was coming from the 3" steel flowline due to external corrosion.

Describe Area Affected and Cleanup Action Taken.*
The spill was not contained and affected approximately 8,000 sq/ft of pasture. The MSO shut in the well and called a vacuum truck to pick up free liquids. 3 bbls of oil and 5 bbls of produced water were recovered. The spill site will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION 	
Printed Name: Mickey Garner	Approved by District ENVIRONMENTAL ENGINEER	
Title: HSER Lead	Approval Date: 11.9.07	Expiration Date:
E-mail Address: Mickey.D.Garner@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11-9-2007	Phone: 505.391.3158	

= RBC = RP#1657