

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company <i>Pogo Producing Co.</i>	Contact <i>Pat Ellis</i>
Address <i>P.O. Box 10340 Midland, Tx 79702</i>	Telephone No. <i>(432) 685-8100</i>
Facility Name <i>Cotton Draw Unit # 9</i>	Facility Type <i>MAIN injection line</i>

Surface Owner	Mineral Owner <i>NEW MEXICO</i>	Lease No. <i>LC-061300</i> <i>API # 30025 08222</i>
---------------	---------------------------------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>E</i>	<i>22</i>	<i>255</i>	<i>32E</i>	<i>1980</i>	<i>North</i>	<i>660</i>	<i>West</i>	<i>LCA</i>

300'

Latitude *32.12887 N* Longitude *103.66624 W*

NATURE OF RELEASE

Type of Release <i>Produced water</i>	Volume of Release <i>20 BBLs</i>	Volume Recovered <i>15 BBLs</i>
Source of Release <i>Injection line LEAK</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>BLM - phone message</i> <i>OCD - phone message</i>	<i>12-4-07 5:30 pm</i>
By Whom? <i>Johnny Burnett</i>	Date and Hour	<i>12-4-07 6:30 pm</i>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
LEAK WAS CAUSED BY hole in line due to CORROSION. LEAK WAS EXCAVATED AND line WAS REPAIRED.

Describe Area Affected and Cleanup Action Taken.*
Injection line leak was discovered 200 yards SW of the Cotton Draw Unit Battery Pumper shut in line and called out VACUUM truck to recover free fluid. Highlander Environmental will assess site for closure workplan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Patrick L. Ellis</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>PATRICK L. ELLIS</i>	Approved by District Supervisor: <i>Chris Williams</i>	
Title: <i>EHS Supervisor</i>	Approval Date: <i>01/25/08</i>	Expiration Date: <i>04/25/08</i>
E-mail Address: <i>ellis.p@pogoproducing.com</i>	Conditions of Approval: <i>Need to replace line</i>	Attached <input type="checkbox"/>
Date: <i>1-22-08</i>	Phone: <i>685-8100</i>	

* Attach Additional Sheets If Necessary

RP# 1758