

**Bishop, Steven M.**

---

**From:** Bishop, Steven M.  
**Sent:** Wednesday, August 15, 2007 2:29 PM  
**To:** 'Johnson, Larry, EMNRD'  
**Subject:** Old Well Bore

Larry,

We had a pulling unit rigged up on our South Hobbs Unit Well #210 last week and while they were there they discovered what appears to be a cased hole with a plate welded on top. This location is in the B J Chemical Yard (old Unichem) and shares the location with South Hobbs Unit #210, South Hobbs Unit Coop #9, and a P X A well South Hobbs Unit #1. We can account for our wells so we do not know if this is an old water well or an abandoned producer from before unitization. It appears a fork lift has damaged the plate that was welded on top of the casing. We wanted to do something with the well since it is on our location but wanted your input first. We thought we would dig around it and cut off the casing so it is well below ground level, fill with cement, and reweld a plate on top. The location is at the intersection of Lea Street and N. Leech in Hobbs, west of the intersection, in the B J Chemical Yard. UL 'D' Sec. 34, T-18-S, R-38-E. I would be happy to meet with you and show you. Please call with any questions or if I can be of any help. Cell 390-4784.

Thanks Steve Bishop  
Oxy Permian LTD  
(505) 397-8251

*OK - Chris Williams  
1/29/08*

*No fluid in the well bore! Close  
weld plate on wellhead - GPS  
Coordinates on UL-S-TR.*

*RP# 1769*

12-5-07 Called Larry Johnson w/ ocd 12/5/07 told him we  
dug out, 85' deep, no water detected Larry asked  
to fence it off & let him discuss w/ WAYNE Price  
SANTA FE. I took (2) photos. SMB