

RP. 2052

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Lanexco Inc.	Contact	Charlie Mann
Address	1308 W. Kansas St. Jct NM	Telephone No.	575-390-3937
Facility Name	Hansford #4 well/BT	Facility Type	Production
Surface Owner	Mary Wantz	Mineral Owner	Wantz
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	21	21	37					lea

Latitude _____ Longitude _____

WRTS'

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	Unknown	Volume Recovered	
Source of Release	Lead lines at Tank Battery	Date and Hour of Occurrence	?	Date and Hour of Recovery	RECEIVED
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?		Historic Release 2009	
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse		HOBBSOCD	

If a Watercourse was Impacted, Describe Fully.*

JAN 20 2009

Describe Cause of Problem and Remedial Action Taken.*

Area in front of tank battery approximately 30x30 where oil had leaked from the lead line on truck spill. (Historical release)

Describe Area Affected and Cleanup Action Taken.*

The contaminated area was excavated and hauled to a OCD approved disposal, sampled and clean soil replaced. Report filed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Eddie W Seay*

Printed Name: Eddie W Seay

Title: Agent

E-mail Address: seay04@leaco.net

Date: 1/20/2009 Phone: 390-2454

Approved by District Supervisor: *[Signature]*

Approval Date: 1.20.09 Expiration Date: _____

Conditions of Approval: _____

Attached IRP # 2052

* Attach Additional Sheets If Necessary

FGRL0902140699

LANEXCO INC.
LANSFORD #4 & BATTERY
SW 1/4 OF SW 1/4 Sect. 21, T. 21 S., R. 37 E.
LEA CO., NM

30-025-26812

FINAL REPORT

RECEIVED

JAN 15 2009

HOBBSOCD

Prepared by
Eddie Seay Consulting
January 2009

January 14, 2009

NMOCD Environmental
ATTN: Mark Whitaker
1625 N. French Drive
Hobbs, NM 88240

RE: Lanexco Inc.
Lansford Battery
NOV


Mr. Whitaker:

Lanexco has completed the cleanup at the above listed battery and well on the NOV sent by the OCD. The cleanup was finished by the deadline. All contaminated soils were hauled to DD Landfarm. A total of forty (40) cu. yds. of soil was excavated, much of which had to be hand dug due to buried lines in close proximity.

Find enclosed photos, final analytical and report.

Should you have any questions, please call.

Sincerely,

A handwritten signature in black ink that reads "Eddie W. Seay". The signature is written in a cursive style with a long, sweeping tail that extends to the right.

Eddie W. Seay, Agent
Eddie Seay Consulting
601 W. Illinois
Hobbs, NM 88242
(575)392-2236
seay04@leaco.net

cc: Lanexco Inc.
Charlie Mann



ANALYTICAL RESULTS FOR
 EDDIE SEAY CONSULTING
 ATTN: EDDIE SEAY
 601 W. ILLINOIS
 HOBBS, NM 88242
 FAX TO: (575) 392-6949


Receiving Date: 01/08/09
 Reporting Date: 01/09/09
 Project Owner: LANEXCO
 Project Name: LANEXCO LANSFORD BATTERY
 Project Location: SECT-21 EUNICE, NM

Sampling Date: 01/07/09
 Sample Type: SOIL
 Sample Condition: COOL & INTACT
 Sample Received By: ML
 Analyzed By: AB/TR

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/kg)	DRO (>C ₁₀ -C ₂₈) (mg/kg)	CI* (mg/kg)
ANALYSIS DATE		01/08/09	01/08/09	01/09/08
H16635-1	LANSFORD #1	<10.0	<10.0	96
Quality Control		453	517	500
True Value QC		500	500	500
% Recovery		90.6	103	100
Relative Percent Difference		3.4	7.4	<0.1

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Std. Methods 4500-CFB

Note: Analysis performed on a 1:4 w:v aqueous extract.


 Lab Director


 Date

H16635 TCL SEAY

PLEASE NOTE. **Liability and Damages.** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

RECEIVED OCT 0 3 2008



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E. Director Oil Conservation Division

Response Required - Deadline Enclosed

Field Inspection Program Preserving the Integrity of Our Environment

01-Oct-08

LANEXCO INC PO BOX 2730 MIDLAND TX 79702

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.


Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.


Table with columns: LANSFORD No., Inspection Date, Type Inspection, Inspector, Violation?, Significant Non-Compliance?, Corrective Action Due By, Inspection No. Includes handwritten '004' and '26812'.

Comments on Inspection: Location needs attention. Equipment OK. Packing at unit leaking. Area around loading valve at battery saturated with oil. NEED TO REMOVE CONTAMINATED SOIL AND DISPOSE OF PROPERLY. ALSO REPAIR PACKING AT WELLHEAD. 1st letter of non-compliance. MW

RP 2052







Final

