

RECEIVED

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87414
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

JAN 13 2009

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>Marbob Energy Corporation</i>	Contact
Address <i>PO Box 227 Artesia, NM 88211</i>	Telephone No.
Facility Name <i>LPC 31 #1</i>	Facility Type
Surface Owner <i>BLM</i>	Mineral Owner <i>BLM</i>
Lease No. <i>nm/nm 23006</i>	

LOCATION OF RELEASE

API 30 025 3740

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>G</i>	<i>31</i>	<i>18s</i>	<i>32E</i>	<i>1980</i>	<i>North</i>	<i>2280</i>	<i>EAST</i>	<i>LEA</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Heater Treater Fire</i>	Volume of Release <i>3-4 barrels</i>	Volume Recovered <i>2-</i>
Source of Release <i>Heater Treater</i>	Date and Hour of Occurrence <i>11/6/09 2:00 PM</i>	Date and Hour of Discovery <i>11/7/09 0700</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Paul Kautz - NMOCD - Hobbs office</i>	
By Whom? <i>Rand French, Marbob</i>	Date and Hour <i>11/7/09 1010 am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Fire started Heater Treater by fire tubing. Released some fluid 3-4 barrels of which some burned, Recovered 2 barrels, while sucking up stand fluid. Pulled the remaining fluid out of treater (7 barrels) and began maintenance.

Describe Area Affected and Cleanup Action Taken.*

Area affected was right around Heater treater, all fluid stayed within the isolated berm area. Removed fluids, gravel and 2" of soil, and replaced with clean material. Hauled off approximately 5 yds of soil + gravel to CRD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Rand French</i>	Approved by District Supervisor: <i>[Signature]</i>	
Printed Name: <i>Rand French</i>	ENVIRONMENTAL ENGINEER	
Title: <i>Biologist</i>	Approval Date: <i>2.18.09</i>	Expiration Date: _____
E-mail Address: <i>wildlife@marbob.com</i>	Conditions of Approval: _____	Attached <input type="checkbox"/> <i>IRP# 09.2.2087</i>
Date: <i>1/9/08</i>	Phone: <i>748-3303</i>	

* Attach Additional Sheets If Necessary

FGRL0905642234