

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 21 2010

HOBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Southern Union Gas Services	Contact: Rose Slade
Address: 1507 West 15 th Street	Telephone No. 432-940-5147
Facility Name : Trunk "O" line	Facility Type: Gathering 30" Pipeline

Surface Owner : Dasco Land Corp.	Mineral Owner	Lease No.
----------------------------------	---------------	-----------

LOCATION OF RELEASE API # 30-02538822-00-00


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	33	21	36					Lea

Latitude 32 25.808 Longitude 103 16.221

NATURE OF RELEASE

Type of Release : Mixture of crude oil/produced water	Volume of Release 126 barrels	Volume Recovered 106 barrels
Source of Release : Leak on 30" pipeline	Date and Hour of Occurrence : 9/17/2010 @ approx. 9:30 am	Date and Hour of Discovery: 9/17/2010
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? D.L. Gonzales	
By Whom? Rose Slade	Date and Hour: 9/18/2010 at 5:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The release was caused by internal corrosion of the 30" steel pipeline. A temporary clamp was utilized to mitigate the release during the initial release response. Following initial response activities (recovering liquids with a vacuum truck) the line will be replaced at a later date.		
Describe Area Affected and Cleanup Action Taken.* The area affected was approximately 20x30feet in width and length and approximately 10 feet in depth. An environmental consultant team will remediate the site per NMOCD regulatory guidelines.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Rose Slade	Approved by <u>ENV ENGINEER:</u> District Supervisor: 	
Title: EHS Compliance Specialist	Approval Date: 09/22/10	Expiration Date: 11/22/10
E-mail Address: rose.slade@sug.com	Conditions of Approval: SUBMIT FINAL C-141 BY 11/22/10	Attached <input type="checkbox"/>
Date: 9/21/2010 Phone: 432-940-5147	IRP-10-9-2612	

* Attach Additional Sheets If Necessary