

District I
1625 N. French Dr., Hobbs, NM
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
JUL 16 2010
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name MCA 4 B Header	Facility Type Oil and Gas

Surface Owner Federal	Mineral Owner Federal	Lease No LC-030437A
------------------------------	------------------------------	----------------------------

LOCATION OF RELEASE

NEARBY MCA UNIT WELL NO. 082

API # 30-025-00644-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	23	17S	32E					Lea

Latitude Longitude

NATURE OF RELEASE

Type of Release Crude oil	Volume of Release 16.3bbl (16.3oil, 0water)	Volume Recovered (12oil, 0water)
Source of Release Seperated collar on a 4" Transite Production Line	Date and Hour of Occurrence 7-13-10 1000	Date and Hour of Discovery 7-13-10 1244
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking NMOCD	
By Whom? John Gates	Date and Hour 7-14-10 1330	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 55'



Describe Cause of Problem and Remedial Action Taken.*

Release originated from a seperated compression fitting on a 4" transite production line located between the 4 B header and battery # 4 due to suspected fatigue/age. A vacuum truck was called and 12 bbls of crude oil was recovered.

Describe Area Affected and Cleanup Action Taken.*

102'x 90'x .5" area of sandy pasture land. A COPC MSO discovered the spill and immediately isolated the line in order to prevent the release of any additional fluids. The spill site will be remediated in accordance with an agreement with BLM and NMOCD

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by <small>ENVI ENGIN SEER</small> District Supervisor: 	
Title: HSER Lead	Approval Date: 07/16/10	Expiration Date: 09/16/10
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: SUBMIT FINAL C-141 BY 09/16/10	Attached <input type="checkbox"/>
Date: 7/14/10 Phone: 505.391.3158		IRP-11-10-2652

- Attach Additional Sheets If Necessary