

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
FEB 16 2011
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nmlb1027952232 OPERATOR Initial Report Final Report

Name of Company COG Operating LLC	Contact Pat Ellis
Address 550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No. (432) 685-4332
Facility Name Tex Mack 11 Federal #35	Facility Type Well

Surface Owner: Federal Mineral Owner Lease No. API 30-015-37667

LOCATION OF RELEASE

Unit Letter M	Section 11	Township 17S	Range 31E	Feet from the 920	North/South Line South	Feet from the 1024	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude N 32 50.659° Longitude W 103 50.721°

NATURE OF RELEASE

Type of Release: Produced Fluids	Volume of Release 70 bbls	Volume Recovered 145 bbls
Source of Release: Wellbore (casing)	Date and Hour of Occurrence 7/27/10	Date and Hour of Discovery 7/27/10 1:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Josh Russo	Date and Hour 7/28/10 10:52 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The well was flowing up the backside and a shallow hole in the 5 1/2 casing allowed fluid to escape into the 8 5/8 casing. The fluid in the 8 5/8 casing then escaped into the wellbore due to an improper seal. The well is in the process of being repaired and put back into service.		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Ike Tavarez</i>	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by District Supervisor Signed By <i>Mike Bratcher</i>	
Title: Project Manager	Approval Date: <i>2/12/2011</i>	Expiration Date: <i>NA</i>
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval: <i>NA</i>	Attached <input type="checkbox"/>
Date: <i>February 16, 2011</i> Phone: (432) 682-4559	<i>Final</i>	

* Attach Additional Sheets If Necessary

2RP-443