

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 26 2009

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-21309

Release Notification and Corrective Action

nkmw 1109433489

Name of Company Seely Oil Company <i>20497</i>		Contact David L. Henderson	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 815 W. 10 th St., Ft. Worth, TX 76102		Telephone No. 817-332-1377		
Facility Name Stevens Federal #2		Facility Type		

Surface Owner Federal	Mineral Owner	Lease No. NM 0384576
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	35	17S	30E	660	North	1980	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil	Volume of Release Approx 5 bbls	Volume Recovered Ø
Source of Release Flowline failure	Date and Hour of Occurrence Unknown	Date and Hour of Discovery May 14, 2009 unknown time
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Mr. Tim Gumm	Date and Hour Unknown	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Unknown persons turned a pumping unit on which caused a flowline failure. Approximately 5 bbls of oil was pumped out of the leak. Seely Oil Company proposes to remove and dispose of the affected soil.

Describe Area Affected and Cleanup Action Taken.*
An area of about 20 feet square around the wellhead and a thin stream about 18" wide by 55' was affected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>David L. Henderson</i>	OIL CONSERVATION DIVISION	
Printed Name: David L. Henderson	Approved by District Supervisor <i>Michelle Beaton</i>	
Title: Executive Vice President	Approval Date: <i>4/4/11</i>	Expiration Date:
E-mail Address: dhenderson@seelyoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/21/2009 Phone: 817-332-1377	REMEDATION per OCD Rules and Guidelines. <u>SUBMIT REMEDIATION PROPOSAL BY:</u>	

* Attach Additional Sheets If Necessary

5/4/11
2RP-689
(1)