

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-33929

Release Notification and Corrective Action

nMLB112542397

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P. <u>260737</u>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit #227	Facility Type E&P <u>SWS</u>

Surface Owner Federal	Mineral Owner Federal	Lease No.
-----------------------	-----------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	30	24S	30E					Eddy

Latitude N 32.18191 Longitude W 103.91429

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 50 bbls produced water.	Volume Recovered: none
Source of Release: 2' poly line connected to a water transfer pump.	Date and Hour of Occurrence 4/19/11, Hour unknown	Date and Hour of Discovery 4/19/11 at 7:29 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
MAY 04 2011

Describe Cause of Problem and Remedial Action Taken.*
A 2" poly line failed where it was connected to a water transfer pump. The pump was shut down causing the flow of water to stop. The poly line was repaired later that evening.

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*
The produced water traveled down a lease road for approximately 900 ft. It then left the road way and entered a rocky gully that averaged about 2 ft. in width where it traveled approximately 1200 ft. before dumping into another wash area, traveled approximately 30 ft. and stopped. The BLM reviewed the area on 4/20/11 and agreed to wash the traverse area down with fresh water and use a vacuum truck to capture the rinsed water at the point where it entered into the wash area. On 4/25/11 approximately 300 bbls of fresh water was used to rinse down the road and gully, a 2" poly line was laid across the pasture to the wash area to capture what water accumulated at the end. The site is pending review by the NMOCD and BLM for Closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor: <u>Mike Brannon</u>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <u>5/5/2011</u>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 5/3/11 Phone: 432-556-8730	<u>6/5/2011</u>	

* Attach Additional Sheets If Necessary

2RP-774