

THOMAS A. DUGAN

Registered Professional Engineer

FARMINGTON, NEW MEXICO

709 BLOOMFIELD BLVD.
OFFICE PH. 325-9184

1007 NORTH DUSTIN
HOME PH. 325-5694

Johnston, William H. Jr.
Civil Engineer

Station	Remarks	Station	Remarks
100+00	0	100+00	0
100+10	.50	100+10	.50
100+20	0	100+20	0
100+30	.50	100+30	.50
100+40	0	100+40	0
100+50	.50	100+50	.50
100+60	0	100+60	0
100+70	.50	100+70	.50
100+80	0	100+80	0
100+90	.50	100+90	.50
101+00	0	101+00	0
101+10	.50	101+10	.50
101+20	0	101+20	0
101+30	.50	101+30	.50
101+40	0	101+40	0
101+50	.50	101+50	.50
101+60	0	101+60	0
101+70	.50	101+70	.50
101+80	0	101+80	0
101+90	.50	101+90	.50
102+00	0	102+00	0
102+10	.50	102+10	.50
102+20	0	102+20	0
102+30	.50	102+30	.50
102+40	0	102+40	0
102+50	.50	102+50	.50
102+60	0	102+60	0
102+70	.50	102+70	.50
102+80	0	102+80	0
102+90	.50	102+90	.50
103+00	0	103+00	0
103+10	.50	103+10	.50
103+20	0	103+20	0
103+30	.50	103+30	.50
103+40	0	103+40	0
103+50	.50	103+50	.50
103+60	0	103+60	0
103+70	.50	103+70	.50
103+80	0	103+80	0
103+90	.50	103+90	.50
104+00	0	104+00	0
104+10	.50	104+10	.50
104+20	0	104+20	0
104+30	.50	104+30	.50
104+40	0	104+40	0
104+50	.50	104+50	.50
104+60	0	104+60	0
104+70	.50	104+70	.50
104+80	0	104+80	0
104+90	.50	104+90	.50
105+00	0	105+00	0
105+10	.50	105+10	.50
105+20	0	105+20	0
105+30	.50	105+30	.50
105+40	0	105+40	0
105+50	.50	105+50	.50
105+60	0	105+60	0
105+70	.50	105+70	.50
105+80	0	105+80	0
105+90	.50	105+90	.50
106+00	0	106+00	0
106+10	.50	106+10	.50
106+20	0	106+20	0
106+30	.50	106+30	.50
106+40	0	106+40	0
106+50	.50	106+50	.50
106+60	0	106+60	0
106+70	.50	106+70	.50
106+80	0	106+80	0
106+90	.50	106+90	.50
107+00	0	107+00	0
107+10	.50	107+10	.50
107+20	0	107+20	0
107+30	.50	107+30	.50
107+40	0	107+40	0
107+50	.50	107+50	.50
107+60	0	107+60	0
107+70	.50	107+70	.50
107+80	0	107+80	0
107+90	.50	107+90	.50
108+00	0	108+00	0
108+10	.50	108+10	.50
108+20	0	108+20	0
108+30	.50	108+30	.50
108+40	0	108+40	0
108+50	.50	108+50	.50
108+60	0	108+60	0
108+70	.50	108+70	.50
108+80	0	108+80	0
108+90	.50	108+90	.50
109+00	0	109+00	0
109+10	.50	109+10	.50
109+20	0	109+20	0
109+30	.50	109+30	.50
109+40	0	109+40	0
109+50	.50	109+50	.50
109+60	0	109+60	0
109+70	.50	109+70	.50
109+80	0	109+80	0
109+90	.50	109+90	.50
110+00	0	110+00	0
110+10	.50	110+10	.50
110+20	0	110+20	0
110+30	.50	110+30	.50
110+40	0	110+40	0
110+50	.50	110+50	.50
110+60	0	110+60	0
110+70	.50	110+70	.50
110+80	0	110+80	0
110+90	.50	110+90	.50