DISTRIBUTION SANTA FE	I ₩ '-'	
		Form C-103 Supersedes Old
	MEW MEYICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-12 ndsC-103 Efficient of the state of the
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Affective 3-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee.
OPERATOR		5. State Oil & Gas Lease No.
or Environ		5. State Off & Gds Lease No.
SUNE (DO NOT USE THIS FORM FOR I USE "APPLIC	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER- Well Plugged and Abandoned	7. Unit Agreement Name
Shell Oil Company	y (Rocky Mountain Division Production)	8. Farm or Lease Name Laguna-Wilson Trust
Address of Operator 1700 Broadway, D	enver, Colorado 80202	9. Well No.
1. Location of Well	2080 FEET FROM THE NORTH LINE AND 1780 FEET FR	10. Field and Pool, or Wildcat Cactus Area (Wildcat)
	FEET FROM THE LINE AND FEET FR	
THE LINE, SEC		
	15. Elevation (Show whether DF, RT, GR, etc.) 5394 GL, 5415 KB	12. County Bernalillo
6. Check	k Appropriate Box To Indicate Nature of Notice, Report or (Pekan Dana
	INTENTION TO	other Data NT REPORT OF:
	99992482	N. K.E. SKY SY.
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
ULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
I Describe Described Control		
WOIN, SEE ROLE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, includi	
On 12-25-72	?, began plugging well as follows: (Class "A", .	004% HR-4)
<u>I</u> n	iterval Sx Cmt (Mud - 9.6#)	
10,	950-10,700 125	
	200-7,100 50	
7,		
	900-6.750 75	
6,	,900–6,750 75 ,050–3,950 75	
6, 4,	050-3,950 75	
6, 4,	050-3,950 75 350-800 25	ag and installed
6, 4, Removed csg dry hole ma	3,950 75 350-800 25 ghd and spotted 10 sx cmt plug at sfc. Plated c orker. Completed plugging 12-26-72. 13 3/8" &	9 5/8" csg left
Removed csg dry hole main hole. A location is	350-3,950 350-800 25 25 26 and spotted 10 sx cmt plug at sfc. Plated carker. Completed plugging 12-26-72. 13 3/8" & at the moment, there are severe muddy conditions ready for inspection, probably July, your offi Laguna Pueblo Indian Reservation P. C. Box 194	9 5/8" csg left
Removed csg dry hole main hole. A location is	350-3,950 350-800 25 ghd and spotted 10 sx cmt plug at sfc. Plated carker. Completed plugging 12-26-72. 13 3/8" & at the moment, there are severe muddy conditions ready for inspection, probably July, your offi Laguna Pueblo Indian Reservation P. O. Box 194 Laguna, New Mexico 37826	9 5/8" csg left
Removed csg dry hole main hole. A location is	350-3,950 350-800 25 36d and spotted 10 sx cmt plug at sfc. Plated corker. Completed plugging 12-26-72. 13 3/8" & at the moment, there are severe muddy conditions ready for inspection, probably July, your offi Laguna Pueblo Indian Reservation P. O. Box 194 Laguna, New Mexico 37826 Bureau of Indian Affairs Southern Pueblo Agency P. O. Box 1667	9 5/8" csg left
Removed cag dry hole ma in hole. A location is cc:	350-3,950 350-800 25 36d and spotted 10 sx cmt plug at sfc. Plated corker. Completed plugging 12-26-72. 13 3/8" & at the moment, there are severe muddy conditions ready for inspection, probably July, your offi Laguna Pueblo Indian Reservation P. O. Box 194 Laguna, New Mexico 37826 Bureau of Indian Affairs Southern Pueblo Agency P. O. Box 1667 Albuquerque, New Mexico 87103 Attention Mr. Albert Maytubby	9 5/8" csg left
Removed cag dry hole ma in hole. A location is cc:	350-3,950 350-800 25 36d and spotted 10 sx cmt plug at sfc. Plated corker. Completed plugging 12-26-72. 13 3/8" & at the moment, there are severe muddy conditions ready for inspection, probably July, your offi Laguna Pueblo Indian Reservation P. O. Box 194 Laguna, New Mexico 37826 Bureau of Indian Affairs Southern Pueblo Agency P. O. Box 1667	9 5/8" csg left
Removed cag dry hole ma in hole. A location is cc: cc:	25 25 260-800 25 26d and spotted 10 sx cmt plug at sfc. Plated carker. Completed plugging 12-26-72. 13 3/8" & the moment, there are severe muddy conditions ready for inspection, probably July, your offi Laguna Pueblo Indian Reservation P. O. Box 194 Laguna, New Mexico 37826 Bureau of Indian Affairs Southern Pueblo Agency P. O. Box 1667 Albuquerque, New Mexico 87103 Attention Mr. Albert Maytubby on above is true and complete to the best of my knowledge and belief.	9 5/8" csg left; however, when the ce will be contacted.
Removed cag dry hole ma in hole. A location is cc: cc:	350-3,950 350-800 25 25 26 26 27 28 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20	9 5/8" csg left; however, when the ce will be contacted.
Removed cag dry hole ma in hole. A Location is cc: cc:	350-3,950 350-800 25 25 26 26 27 28 28 29 29 20 20 20 20 20 20 20 20 20 20 20 20 20	9 5/8" csg left; however, when the ce will be contacted.