

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAY - 9 1977
CONSERVATION COMMISSION
Santa Fe

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		5. State Oil & Gas Lease No. <u>N/A</u>
2. Name of Operator <u>TransOcean Oil, Inc.</u>		7. Unit Agreement Name <u>None</u>
3. Address of Operator <u>1700 First City East Bldg., 1111 Fannin, Houston, Texas 77002</u>		8. Farm or Lease Name <u>Turner SFPRR</u>
4. Location of Well UNIT LETTER <u>F</u> <u>1559.7</u> FEET FROM THE <u>North</u> LINE AND <u>1571.5</u> FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>3N</u> RANGE <u>9W</u> NMPM.		9. Well No. <u>1</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>7130' GL</u>		10. Field and Pool, or Wildcat <u>Wildcat</u>
12. County <u>Catron</u>		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐
 OTHER ☐

PLUG AND ABANDON ☒
 CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Received verbal permission May 4, 1977 from New Mexico Conservation Comm. in Santa Fe to P & A well (Mr. Carl Ulvog).

Plugging procedure to be followed:

- (1) Set cmt plug w/ 40 sx @ 4850-4690' (9# mud)
 Set cmt plug w/ 40 sx @ 2830-2670' (9# mud)
 Set cmt plug w/ 40 sx @ 2480-2320' (9# mud)
 Set cmt plug w/ 40 sx @ 1080-920' (9# mud)
 Set cmt plug w/ 30 sx @ 565-435' (9# mud)
 Set cmt plug w/ 10 sx @ surface w/ dry hole marker (9# mud)
- (2) A steel marker to be placed 4' above ground level.
- (3) Loc to be cleared of all junk and pits filled and loc to be leveled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. S. Jones TITLE Mgr, Western Drlg. Div. DATE 5/6/77
 APPROVED BY Carl Ulvog TITLE SENIOR PETROLEUM GEOLOGIST DATE 5/9/77
 CONDITIONS OF APPROVAL, IF ANY: