Submit 3 Copies to Appropriate District Office

CONDITIONS OF AFFROYAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89 OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO. P.O. Box 2088 30-003-20018 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease DISTRICT III STATE FEE 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. LH-3057 SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Weil: OIL. X WELL OTHER 2. Name of Operator 8. Well No. HUNT OIL COMPANY 3. Address of Operator 9. Pool name or Wildcat P.O. Box 720420, Norman, Oklahoma 73070-4307 Well Location Wildcat Unit Letter P : 1090 Feet From The South 660 \_ Line and Feet From The East 16 Section ship 3S Range 13W
10. Elevation (Show whether DF, RKB, RT, GR, etc.) Township NMPM Catron County 7573' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed T.D. 6890'. 9-5/8" csg set @ 4563' (no casing was pulled). MW 9.2, Vis 45. RIH w/open ended drill pipe and set 7 cement plugs using total of 210 sxs premium cement with 6#/salt per sack and .3% CFR-3. Slurry wt 15.6 ppg. Plug #1 25 sxs 6873' (T.D.) Plug #5 25 sxs 3913' (San Andres) #2 25 sxs 5791' (Abo) #3 45 sxs 4611' (Yeso/Csg) #6 45 sxs 3690' (Chinle/Dakota) #7 20 sxs 1888' (cmt outside 9-5/8") #4 25 sxs 4326' (Glorietta) Cut off wellhead (4' below G.L.). Weld plate on csg stub. Affidavit of responsibility is being processed to leave wellbore for ranchers use as water well. Rig moved from drill site. Will let pit dry before reclaiming drill site. 4-11-91 - location OK R&G SKINATIJE mms District Superintendent DATE 11/17/89 TYPE OR FRINT NAME C.D. Williams 405/387-5888 TELEPHONE NO. (This space for State Use) DISTRICT SUPERVISOR