NO. OF COPIES RECEIVED	
	Form C-103
DISTRICUTION	Supersedes Old
SANTA TE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE INCIDENCE OF CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	(=
	5a. Indicate Type of Lease
LAND OFFICE	State X Fee.
OPERATOR /	5. State Oil & Gas Lease No.
	L-5399
SUNDRY NOTICES AND DEPORTS ON WELLS	mminim
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL OTHER. Wildcat	7. Unit Agreement Name
well well other. Wildcat. 2. Name of Operator	none
	8. Farm or Lease Name
Roy M Eieal	State
3. Address of Operator	9. Well No.
Box 2087 Albuquerque N M	
4. Location of Well	32
W 660 For 660	10. Field and Pool, or Wildcat
UNIT LETTER M 669 FEET FROM THE FSL LINE AND 660 FEET FR	Wildcat
FEET FR	mmmmmmm ^M
THE FWL LINE, SECTION 32 TOWNSHIP 9N BANGE	
THE FWL LINE, SECTION 32 TOWNSHIP 9N RANGE 15W NMP	
15. Elevation (Show whether DF, RT, GR, etc.)	
GL 7190	12. County
16.	Valencia ()()()
Check Appropriate Box To Indicate Nature of Notice, Report or C	then Date
NOTICE OF INTENTION TO:	iller Data
SUBSEQUE	T REPORT OF:
PERFORM REMEDIAL WORK	_
REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	_
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includit work) SEE RULE 1103.	
work) SEE RULE 1603.	g estimated date of starting any proposed
Plugged in accordance with verbal telephone instruc	ions
from District Supervisor NM Oil & Conservation Comm	
	gin
Santa Ta N Mar.	skion
Sante Fe N Mex.	skion
Sante Fe N Mex.	sion
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru	sion
Sante Fe N Mex.	sion
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru	sion
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows:	skion 1 OD IF
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru prill Pipe as follows: 3050-2800 250 15.5#	skion 2 OD IF 0 kax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5#	skion ODIF Sax Osax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5#	skion DODIF Okak
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5#	skion O Sax O sax 5 sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5#	sion ONE ONE SAX SAX SAX SAX SAX
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5#	skion O Sax O sax 5 sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface "	Signon O Sax O sax Sax O sax O sax O sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface " 6-3/4" Hole filled with mud during plugging operations	skion ODIF Sax sax sax sax sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface " 6-3/4" Hole filled with mud during plugging operations of the sement plugs displaced with mud. Mud properties: Vi	skion ODIF Sax sax sax sax sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface "	skion ODIF Sax sax sax sax sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface " 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Visioner weight 10.1# Wtr Loss 9 cc FC 2/32".	skion O Sax O sax Sax O sax O sax O sax O sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface " 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vision Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 41 OD Dry	skion O Sax O sax Sax O sax O sax O sax O sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface " 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vi: Weight 10.1# Wtr Loss 9 cc FC 2/32". 104: 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	skion O Sax O sax Sax O sax O sax O sax O sax O sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface " 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Visweight 10.1# Wtr Loss 9 cc FC 2/32". 104: 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	skion O Sax O sax Sax O sax O sax O sax O sax O sax
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface " 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Visweight 10.1# Wtr Loss 9 cc FC 2/32". 104: 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	skion Color of the skin of th
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vision Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	Stion O Sax O sax Sax O sax O sax Hole Marker cemented
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vision Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	Stion O Max O Sax O Sax O Sax O Sax May 25 1971
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vision Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	Stion O Max O Sax O Sax O Sax O Sax May 25 1971
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vision Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	Stion O Max O Sax O Sax O Sax O Sax May 25 1971
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vision Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	Stion O Max O Sax O Sax O Sax O Sax May 25 1971
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vir Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	Stion O Max O Sax O Sax O Sax O Sax May 25 1971
Sante Fe N Mex. May 22 1971 - Halliburton pumped cement plugs thru Drill Pipe as follows: 3050-2800' 250' 15.5# 975-950' 25' 15.5# 560'-460' 100' 15.5# 133'-83' 50' 15.5# Surface 6-3/4" Hole filled with mud during plugging operation cement plugs displaced with mud. Mud properties:Vision Weight 10.1# Wtr Loss 9 cc FC 2/32". 104' 8-5/8 Surf Casing left in hole with 4½" OD Dry in top with ten sax.	Stion O Max O Sax O Sax O Sax O Sax May 25 1971