


NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		✓
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65



5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. COM-  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Abandoned Well	7. Unit Agreement Name
2. Name of Operator ODESSA NATURAL CORPORATION	8. Farm or Lease Name ODESSA NATURAL CORP. W. S. RANCH
3. Address of Operator P. O. Box 3908, Odessa, Texas 79760	9. Well No. 4
4. Location of Well UNIT LETTER N 2100 FEET FROM THE West LINE AND 990 FEET FROM THE South LINE, SECTION 12 TOWNSHIP 29N RANGE 18E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR 7841' KB 7854'	12. County Colfax

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

AUGUST 1, 1972 TD 6196' PBTD 2530'

It is intended to plug and abandon this well as follows:

- (1) Cut off 9-5/8" OD casing at free point.
- (2) Set 35 sxs regular cement plug at 9-5/8" OD stub.
- (3) Set 50 sxs regular cement plug 95' to 205'.
- (4) Set 5 sxs regular cement plug at surface w/4" OD x 4' high dry hole marker.

## Distribution:

3/NMOCC-Santa Fe, 1/WSRanch, 1/RLH, 1/JH, 1/JJS, 2/LC, 1/WF

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John J. Strojek TITLE MANAGER - PRODUCTION DEPT. DATE 8/1/72  
JOHN J. STROJEK  
APPROVED BY J. E. Kaptana TITLE Oil & Gas Inspector DATE 8/3/72  
DISTR. IV  
CONDITIONS OF APPROVAL, IF ANY: