

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

OIL CONSERVATION COMM  
Santa Fe

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole	7. Unit Agreement Name
2. Name of Operator ODESSA NATURAL CORPORATION	8. Farm or Lease Name Odessa Natural Corp.
3. Address of Operator P. O. Box 3908, Odessa, Texas 79760	9. Well No. 5
4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>363</u> FEET FROM THE <u>East</u> LINE, SECTION <u>22</u> TOWNSHIP <u>30N</u> RANGE <u>18E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR 7943' KB 7956'	12. County Colfax

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

October 25, 1972 TD 6388' PBD 2461' COTD 2344'

It is intended to plug and abandon this well as follows:

- (1) Set 40 sx regular cement plug 2120' to 2220' (Perforations 2130' - 2220').
- (2) Cut off 9-5/8" OD casing at free point and recover casing.
- (3) Set 40 sack regular cement plug on top of 9-5/8" OD casing stub.
- (4) Set 55 sack regular cement plug 95' to 195' (bottom of surface casing).
- (5) Set 5 sack regular cement plug at surface w/4" OD x 4' high dry hole marker.

Distribution:

3/NMOCC-Santa Fe, 1/WSRanch

1/KH, 1/RLH, 1/JH, 1/EB, 1/JJS, 1/WF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John J. Strojek TITLE Manager - Production Dept. DATE 10/25/72  
JOHN J. STROJEK/50  
APPROVED BY B. Kapteina TITLE Oil & Gas Inspector DATE 10/27/72  
CONDITIONS OF APPROVAL IF ANY: