DISTRIBUTION	1 1 1		•	Form C-103	
SANTA FE	NEW MEXICO OIL CONSERVATION COM			Supersedes Old Cile3 and C-103	
FILE		HEM WEXICO OIL CONSER	RYATION COMMISSION	Effective 1-1-65	
y.s.g.s.					
LAND OFFICE	 			Sa. Indicate Type of Lease	
OPERATOR	+			State Fco K	
	 J			5. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL SET O DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" IFORM C-TOIL FOR SUCH PROPOSALS.)					
OIL GAS WELL WELL	7. Unit Agreement Name				
Bennett Pe	Phelps Dodge				
1776 Lincoln Street, Denver, Colorado 80203				9. Well No.	
Location of Well	1				
UHIT LETTER	10. Field and Pool, or Wildcat Wildcat				
THE South	INE, SECTION24	township 28 N.	RANGE 20 E N	MPM.	
TITTIIIIII		15. Elevation (Show whether DF,		12. County	
		6366' GR, 6373'	KB	Colfax	
	Check Appropria	ate Box To Indicate Natu	re of Notice, Report or	Other Data	
NOTIC	E OF INTENTIO	N TO:		ENT REPORT OF:	
NOW JAIDEMEN MEGENE]	PLUG AND ABANDON RE	MEDIAL WORK	·	
EMPORARILY ABANDON		-1	MMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT	
ULL OR ALTER CASING	ļ	CHANGE PLANS CA	SING TEST AND CEMENT JOS	TOO AND ABANDONMENT	
			Tem poraril	y Abandoned	
OTHER	·			<u> </u>	
	npleted Operations (C	learly state all pertinent details,		y Abandoned X ding estimated date of starting any propose	
Describe Proposed or Comwork) see RULE 1103. Temporarily Well, accom	, abandoned : rding to instr	with junk in hole at	and give pertinent dates, inclusively and give pertinent dates.	ding estimated date of starting any propose	
Describe Proposed or Comwork) SEE RULE 1103. Temporarily well, accomposed or Comwork) SEE RULE 1103.	abandoned rding to instruction which time	with junk in hole at ructions received fro we hope to have a	and give pertinent dates, inclu 2920'. We antic om your office, du drilling rig in the	ding estimated date of starting any proposed ipate plugging this ring the first quarter area to do further	
Temporarily well, accorded of the drilling.	abandoned rding to instruction which time	with junk in hole at ructions received fro we hope to have a <u>Gas Shows</u> :	and give pertinent dates, included a 2920'. We anticome your office, dudrilling rig in the Set surface case	ipate plugging this ring the first quarter area to do further	
Describe Proposed or Comwork) SEE RULE 1103. Temporarily well, accomposed of 1978, at drilling. Sample Top	v abandoned rding to instr which time	with junk in hole at ructions received fro we hope to have a	2920'. We anticom your office, dudrilling rig in the	ipate plugging this ring the first quarter area to do further sing at 150' K.B. w/100 coment 3% CaCl.	
Temporarily well, according. Sample Top Niobrara, Apishapa, Carlile	r abandoned rding to instruction which time s: 1655' 1850' 2525'	with junk in hole at ructions received fro we hope to have a <u>Gas Shows:</u> 1200-1620'	2920'. We anticom your office, dudrilling rig in the	ipate plugging this ring the first quarter area to do further sing at 150' K.B. w/100 coment 3% CaCl.	
Temporarily well, according of 1978, at drilling. Sample Top Niobrara, Apishapa,	r abandoned rding to instruction which time s: 1655' 1850' 2525'	with junk in hole at ructions received from we hope to have a Gas Shows: 1200-1620' 2020	and give pertinent dates, included and give pertinent dates, included and give pertinent dates, included and give and gi	ipate plugging this ring the first quarter area to do further sing at 150' K.B. w/100 c cement 3% CaCl.	
Temporarily well, according. Sample Top Niobrara, Apishapa, Carlile	y abandoned rding to instruction which time s: 1655' 1850' 2525'	with junk in hole at ructions received from we hope to have a <u>Gas Shows:</u> 1200-1620' 2020 2640	2920'. We anticom your office, dudrilling rig in the	ipate plugging this ring the first quarter area to do further sing at 150' K.B. w/100 c cement 3% CaCl.	
Temporarily well, according. Sample Top Niobrara, Apishapa, Carlile Dakota Sd. Total Depth	abandoned rding to instruct which time s: 1655' 1850' 2525' , 2914' , 2920' - Please do	with junk in hole at ructions received from we hope to have a <u>Gas Shows:</u> 1200-1620' 2020 2640	2920'. We anticom your office, dudrilling rig in the Set surface cas sacks of regular Plug down at 2. Encountered Wathis time.	ipate plugging this ring the first quarter area to do further sing at 150' K.B. w/100 c cement 3% CaCl.	
Temporarily well, according. Sample Top Niobrara, Apishapa, Carlile Dakota Sd. Tight Hole	abandoned rding to instruct which time s: 1655' 1850' 2525' , 2914' , 2920' - Please do	with junk in hole at ructions received from the week hope to have a Gas Shows: 1200-1620' 2020 2640 2920 not release data at	2920'. We anticom your office, dudrilling rig in the Set surface cas sacks of regular Plug down at 2. Encountered Wathis time.	ipate plugging this ring the first quarter area to do further sing at 150' K.B. w/100 c cement 3% CaCl.	

ONDITIONS OF APPHOVAL, IF ANY: