

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
-	
7. Unit Agreement Name	
-	
8. Farm or Lease Name	
Phelps-Dodge	
9. Well No.	
3	
10. Field and Pool, or Wildcat	
Wildcat	
12. County	
Colfax	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	
2. Name of Operator	
Bennett Petroleum Corp.	
3. Address of Operator	
Suite 630, 1580 Lincoln St., Denver, CO 80203	
4. Location of Well	
UNIT LETTER P 1209 FEET FROM THE South LINE AND 945 FEET FROM	
THE East LINE, SECTION 9 TOWNSHIP 28 N RANGE 21 E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
6564 GR, 6575 KB	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On or about 4/15/85, move in and rig up completion unit. Install new rubber in 10 3/4" x 7" casing head. Run open-ended tubing to 1660'. Circulate well with 9.2 lb/gal mud from 1660' to 650'. Set 25-sack plug from 650' to 518'. Fill well with 9.2 lb/gal mud from 518' to surface. Set 10-sack cement plug with dry-hole marker at surface. Squeeze 10 sacks cement in 10 3/4" x 7" annulus. Clean up surface. Remove rig anchor. Arrange for inspection by a representative of the Commission.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.E. Bennett TITLE President DATE 3/26/85

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 3-29-85

CONDITIONS OF APPROVAL IF ANY: