STATE OF NEW MEXICO

| ENERGY AND MINERALS DEPARTME | | ATION DIVISION | |
|---|---|---|--|
| as, or torics etclives | | OX 2088 | Form C-103 |
| DISTRIBUTION | | | Revised 10-1-78 |
| SANTA FE | SANTA PE, NE | W MEXICO 87501 | Sa. Indicate Type of Lease |
| u.s.g.s. | | , | State Fee K |
| LAND OFFICE | | | 5. State Oil 6 Gas Lease No. |
| OPERATOR | - | • . | 5. State Off & Gds Canse No. |
| | Y NOTICES AND REPORTS O | S BACK YO A DIFFERENT RESERVOIR. | |
| OIL CAS X | OTHER• | | 7. Unit Agreement Name |
| 2. Name of Operator | 8. Farm or Lease Ivame | | |
| Perma Energy Managemen | Kaiser | | |
| 3. Address of Operator | 9. Well No. | | |
| 2200 NW 50th, Suite 200, Oklahoma City, OK 73112 | | | 1-Y |
| 4. Location of Weil | | | 10. Pield and Pool, or Wildcat |
| | 625 EAST | 740 | Wildcat |
| UNIT LETTER | FEET FROM THE | LINE AND PEET PRO | |
| SOUTH | 13 29 | 9N 21E | |
| THE LINE, SECTION | TOWNSHIP | 3\$HAR | |
| mmmm | 15. Elevation (Show wheth | er DF, RT, GR, etc.) | 12. County |
| | 6786' | | Colfax () |
| 16. Check | Appropriate Box To Indicate | Nature of Notice, Report or O | ther Data |
| | TENTION TO: | | IT REPORT OF: |
| | | | ALTERING CASING |
| PERFORM REMEDIAL WORK | PLUG AND ASANDON | A REMEDIAL WORK | PLUG AND ABANDONMENT |
| TEMPORARILY ABANDON | | COMMENCE DRILLING OPHS. | PEUG AND ISANDONMENT |
| PULL OR ALTER CASING | CHANGE PLANS | CASING TEST AND CEMENT JOB | |
| | _ | OTHER | |
| OTHER | | 4 | |
| 17. Describe Proposed or Completed Opwork) SEE RULE 1103. | erations (Clearly state all pertinent d | etails, and give pertinent dates, including | ig estimated date of starting any proposed |
| | | | • |
| | | | |
| Shut-in gas well i | requesting temporary abo | andonment status. | |
| - | | | |
| | | | |
| | | | |
| | | | |

| i T | AUTHORIZATION FOR MAINTENANCE IN SHUT-LE CALE | | |
|---|---|--------------|--|
| 18. I hereby certify that the information above is true and compi | Drlg./Prod. Engineer | 7-10-85 | |
| Ley Ejohnson | DISTRICT SUPERVISOR | DATE 7-26-85 | |