State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

District Office	
DISTRICTI P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088	WELL API NO. 30-007-20095
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	STATE FEE A 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OTHER Coal Methane	7. Lease Name or Unit Agreement Name Castle Rock Park 3118
2. Name of Operator	8. Well No.
Pennzoil Exploration and Production Company	311-M
3. Address of Operator P.O. Box 2967, Houston, TX 77252	9. Pool name or Wildcat Wildcat
4. Well Location	0 West
Unit Letter M: 747 Feet From The South Line and	Feet From The Line
Section 31 Township 31N Range 18E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 8568 GR	NMPM Colfax County
11. Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: SUI	Report, or Other Data BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN	G OPNS. X PLUG AND ABANDONMENT
CHANGE PLANS COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING CASING CASING TEST AND COMMENCE DRILLING CASING CA	G OPNS. X PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN	EMENT JOB X Ing completed X
COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND COMMENCE D	ing completed Z jts (44.5') 11 3/4", 42 lb. 15.8 ppg. 30') 8 5/8", 24 lb. J-55, ST&C locele @ 15.8 ppg. Cement to sure drop) 5, LT&C casing w/343 sks @ 11 pp
CASING TEST AND COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND COMMENCE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclinerally SEE RULE 1103. 6-12 Spud. Drill 14 3/4" hole to 44.5'. Set and cement H-40, ST&C conductor w/64 sks class G w/3% CaCl @ 6-13 Drilled 11" hole to 335'. Set and cement 12 jts (3 casing w/178 sks class G w/2% CaCl and 1/4 lb sk f surface. Bumped plug w/500 psi. 6-28 Test casing and BOP w/600 psi for 30 mins. No press 7-13 Drill 7 7/8" hole to 2065'. (Multiple rig problems 7-15 Set and cement 76 jts (2033.3') 5 1/2", 17 lb. 1-5 Cement to surface. Bumped plug w/1000 psi. Shut do	ing completed Z jts (44.5') 11 3/4", 42 lb. 15.8 ppg. 30') 8 5/8", 24 lb. J-55, ST&C locele @ 15.8 ppg. Cement to sure drop) 5, LT&C casing w/343 sks @ 11 pp

DISTRICT SUPERVISOR 7-25-89