Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

District Office	•	K(1000 1-1-0)	
OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240		WELL API NO.	
P.O. Box 2088		30-007-20105	
DISTRICT II P.O. Drawer DD, Artesia, NM 28210 Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease	
DISTRICT III		STATE FEE X	
1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		T. Land Marie and Michael and	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name CAstle Rock 3117	
(FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:		- CASCIE ROCK JII/	
OIL OUS Coal Methane			
2. Name of Operator		8. Well No.	
Pennzoil Exploration & Production Company		271-G	
3. Address of Operator		9. Pool name or Wildcat	
P.O. Box 2967, Houston, TX 77252		Wildcat	
1770			
Unit Letter _ G : 1750 Feet From The _ N	orth Line and 20	89 Feel From The East Line	
Section 27 Township 31N	n 17F	0-16	
Section 2/ Township 31N Range 17E NMPM Colfax County 10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
8/////////////////////////////////////			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
		SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABAND	ON X REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING	. —	CASING TEST AND CEMENT JOB	
OTHER:	CASING TEST AND CI	<u> </u>	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
8/23/91 Estimated start of work.			
1. Remove surface equipment pull made 1			
2. Set CIDP (0 1460) with 12 eke (1001) along A 0 15 (
2. Set CIBP @ 1460' with 12 sks (108') class A @ 15.6 ppg. Fill to surface with Gel mud. 3. Place 6 sks(50') surface plug with class A @ 15.6 ppg. 4. Place well market fill.			
4. Place well marker, fill pits, remove junk and debris from location.			
, , , , , , , , , , , , , , , , , , , ,	ve Jank and debits if	om location.	
	•		
\cdot			
·			
•			
I hereby earlify that the jaformation shows in true and compiled to the best of my boundaries and build			

TYPE OR PRINT NAME

L. D. Williamson

TELEPHONE NO. 376-2817

ONDITIONS OF APPROVAL, FANTS

TITLE

Operations Superintendent

DATE 7/09/91

TOTAL OPERATIONS SUPERVISOR

TOTAL OPERATIONS OF APPROVAL FANTS