Office District I Energy, Minerals and Natural Resources	D : 134 1 65 1000
The state of the s	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 811 South First Artesia NM 87210 OIL CONSERVATION DIVISION	30-007-20113
811 South First, Artesia, NM 87210 OTL CONSERVATION DIVISION District III 2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brayos 2d Aztec NM 97410	STATE 🔲 FEE 🔳
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	7. Lease Name or Unit Agreement Name: VPR 'A'
Oil Well Gas Well Other COALBED METHANE 2. Name of Operator	
SONAT RATON, LLC	8. Well No. 05
3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 190; RATON, NM 87740	3. I doi name of windcat
4. Well Location	
Unit Letter_G_:1548'feet from theNORTH line and1363'feet from theEAST line Section 36	
8092' (GR)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL V	
TEMPORARILY ABANDON	EDRILLING OPNS. PLUG AND
DILL OF ALTER CACING AND TIPLE	ABANDONMENT
PULL OR ALTER CASING	
OTHER: CONTINUE OTHER: RE	STORATION
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. ROY JOHNSON GRANTED VERBAL PERMISSION AND INSTRUCTIONS TO P&A THIS WELL.	
MIRU Leed rig. TIH w/tubing. Halliburton set 40 sk cement plug from 2150'-2000' and a 75 sk plug from 1061'-700'. TOH & WOC.	
Tagged second plug at 1148'. Halliburton set another 75 sk plug from 1063'-700'. TOH & WOC.	
Tagged plug at 750'. Halliburton set the shoe plug from 400'-300'. (8 5/8" shoe at 354'.) WOC. Tried to fill the hole and was not successful. Obtained permission from Roy Johnson to set CIBP at the bottom of the surface pipe.	
07/01/99 Set CIBP at 325'. Dumped 10' of cement on top of plug. Halliburton set a 10 sk surface plug from 30'-0'.	
RESTORATION: The location has been restored back to or very close to the origina The location has been seeded and grass has started to grow.	l state as far as dirt work.
I hereby certify that the information above is true and complete to the best of my known	wledge and belief.
SIGNATURE DR L. ed J TITLE SR. PETROLEUM ENGINEER DATE 10/04/99	
Type or print name: DON LANKFORD	Telephone No.: (505) 445-4621
(This space for State use)	
APPPROVED BY Ty Conditions of approval, if any	