Johnson, Roy

From: Ordemann, Bill [Bill.Ordemann@ElPaso.com]

Sent: Tuesday, August 14, 2001 5:29 PM

To: 'Johnson, Roy'

Cc: Mitchell, Shirley; Duckworth, James

Subject: RE: Well B-32

Roy,

You are correct. We did not include this well in our test cases and had no intention to do so. We have made an error (Mr. Jones) adding a written frac report to this well that did not belong. There is no perforation record or Halliburton frac record for an interval from 1784'-1786'(there is no coal in this well in this interval!). Please accept my apology, we have done alot of work and have gotten confused on this one. I will get with Brian and figure out which well this stage belongs to and make any necessary corrections on the sundry reports.

We will submit an amended set of reports for B-32 for your approval as soon as possible.

----Original Message----

From: Johnson, Roy [mailto:REJOHNSON@state.nm.us]

Sent: Tuesday, August 14, 2001 3:31 PM

To: Ordemann, Bill Subject: Well B-32

Bill, the reports I just received from you show that this well has been perforated in the Lower Raton and the Vermejo section. I do not recall this well being one of our test candidates. Please give me a call when you have the time. ROY

This email and any files transmitted with it from the ElPaso Corporation are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the sender.
