Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals a	and Natural Resour	ces WELL AP	Revised March 25, 1999 I NO. 30-007-20240
District II	OIL CONSERV	ATION DIVISIO)N	
District III 2040 South Pacheco		5. Indicate	Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			ATE FEE	
2040 South Pacheco, Santa Fe, NM 87505		,	6. State	Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other COALBED METHANE			7. Lease N	Name or Unit Agreement Name: VPR B
2. Name of Operator			8. Well N	o. 37
3. Address of Operator	ENERGY RATON, L.L	,.C.	9. Pool na	me or Wildcat
P.O. BOX	190; RATON, NM 877	40		
4. Well Location				
Unit Letter <u>D</u> : 10	070 feet from the <u>No</u>	orth line and	834 feet from the	<u>West</u> line
Section 26 Townsh	nip 30N Range	18E NMF		COLFAX
	10. Elevation (Show w		, GR, etc.)	
11 Check An	propriate Box to Inc	8064' (GR)	latice Report or	Other Data
NOTICE OF INT				T REPORT OF:
PERFORM REMEDIAL WORK		REMEDIA	AL WORK	☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK				□ ALTERING CASING □ S. □ PLUG AND □
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON	COMMEN	AL WORK NCE DRILLING OPN TEST AND	☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS MULTIPLE	COMMEN	AL WORK NCE DRILLING OPN TEST AND	□ ALTERING CASING □ S. □ PLUG AND □
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE	COMMENT CASING CEMENT	AL WORK NCE DRILLING OPN TEST AND	ALTERING CASING S. PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ond Log. PBTD at 241 age: 2283'-2285'; 224 ge: Pumped 750 gal. Foam with 104,06	COMMENT CASING CEMENT OTHER: 1'. TOC at the surfa 99'- 2306'; 2326'- 23 s of 7.5% HCL acid;	AL WORK NCE DRILLING OPN TEST AND JOB ce. 330' dropped 78 ball seal	ALTERING CASING S. PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. 05/03/01 Patterson ran a Cement B 05/22/01 Patterson perf'd the 1 st sta Maverick frac'd the 1 st sta	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ond Log. PBTD at 241 age: 2283'- 2285'; 229 age: Pumped 750 gal. Foam with 104,000 production.	COMMENT CASING CEMENT OTHER: 1'. TOC at the surfactor of 16/30 mesh	AL WORK NCE DRILLING OPN TEST AND JOB ce. 330' dropped 78 ball seal sand at 21 bpm, w/A	ALTERING CASING S. PLUG AND ABANDONMENT COMPLETION ers; 70 quality nitrogen ATP 2288 psi, ISIP 2,000 psi.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. 05/03/01 Patterson ran a Cement B 05/22/01 Patterson perf'd the 1 st sta Maverick frac'd the 1 st sta Well is ready to be put on	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ond Log. PBTD at 241 age: 2283'-2285'; 229 ge: Pumped 750 gal. Foam with 104,000 production.	COMMENT CASING CEMENT OTHER: 1'. TOC at the surfactor of 7.5% HCL acid: 00 lbs of 16/30 meshiple te to the best of my the company of the com	AL WORK NCE DRILLING OPN TEST AND JOB ce. 330' dropped 78 ball seal sand at 21 bpm, w/A	ALTERING CASING S. PLUG AND ABANDONMENT COMPLETION ers; 70 quality nitrogen ATP 2288 psi, ISIP 2,000 psi.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. 05/03/01 Patterson ran a Cement B 05/22/01 Patterson perf'd the 1 st sta Maverick frac'd the 1 st sta Well is ready to be put on	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ond Log. PBTD at 241 age: 2283'-2285'; 229 age: Pumped 750 gal. Foam with 104,000 production. above is true and completed.	CASING CEMENT OTHER: 1'. TOC at the surfa 99'- 2306'; 2326'- 23 s of 7.5% HCL acid; 00 lbs of 16/30 mesh ete to the best of my	AL WORK NCE DRILLING OPN TEST AND JOB ce. 330' dropped 78 ball seal sand at 21 bpm, w/A	ALTERING CASING S. PLUG AND ABANDONMENT COMPLETION ers; 70 quality nitrogen ATP 2288 psi, ISIP 2,000 psi.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. 05/03/01 Patterson ran a Cement B 05/22/01 Patterson perf'd the 1 st sta Maverick frac'd the 1 st sta Well is ready to be put on I hereby certify that the information a	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ond Log. PBTD at 241 age: 2283'-2285'; 229 age: Pumped 750 gal. Foam with 104,000 production. above is true and completed.	CASING CEMENT OTHER: 1'. TOC at the surfa 99'- 2306'; 2326'- 23 s of 7.5% HCL acid; 00 lbs of 16/30 mesh ete to the best of my	AL WORK NCE DRILLING OPN TEST AND JOB ce. 330' dropped 78 ball seal sand at 21 bpm. w/A	ALTERING CASING S. PLUG AND ABANDONMENT COMPLETION ers; 70 quality nitrogen ATP 2288 psi, ISIP 2,000 psi.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. 05/03/01 Patterson ran a Cement B 05/22/01 Patterson perf'd the 1 st sta Maverick frac'd the 1 st sta Well is ready to be put on I hereby certify that the information a SIGNATURE Type of print name: William M	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ond Log. PBTD at 241 age: 2283'-2285'; 229 ge: Pumped 750 gal. Foam with 104,09 production. TITLE Ordemann	COMMENT CASING CEMENT OTHER: 1'. TOC at the surfa 99'- 2306'; 2326'- 23 s of 7.5% HCL acid; 00 lbs of 16/30 mesh ete to the best of my Engineer Tele	AL WORK NCE DRILLING OPN TEST AND JOB ce. 330' dropped 78 ball seal sand at 21 bpm, w/A knowledge and belie DATE 07.0 ephone No.: (505) 4	ALTERING CASING S. PLUG AND ABANDONMENT COMPLETION ers; 70 quality nitrogen ATP 2288 psi, ISIP 2,000 psi.