

## OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

|                                |                                         |
|--------------------------------|-----------------------------------------|
| 5a. Indicate Type of Lease     |                                         |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |                                         |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)OIL WELL ☐ GAS WELL ☐ OTHER- WILDCAT

Name of Operator

TRANS PECOS RESOURCES, INC.

Address of Operator

11,251 RICHMOND, SUITE F-102, HOUSTON, TX. 77082

Location of Well

UNIT LETTER G 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM  
THE EAST LINE, SECTION 2 TOWNSHIP 9N RANGE 23E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

LATIGO RANCH BLK. A

9. Well No.

1

10. Field and Pool, or Wildcat

WILDCAT

15. Elevation (Show whether DF, RT, GR, etc.)

4871 GR, 4887 KB

12. County

GUADALUPE

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐REMEDIAL WORK ☐ALTERING CASING ☐TEMPORARILY ABANDON ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☐PULL OR ALTER CASING ☐CHANGE PLANS ☐CASING TEST AND CEMENT JOB ☒OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

PRODUCTION CASING: SET 7171 FT. OF 5 1/2", J-55, LT & C,  
RANGE 3 CASING AT 7187 FT. (GL). USED HALLIBURTON GUIDE SHOE,  
FLOAT COLLAR AND 22 CENTRALIZERS. CEMENTED WITH TWO STAGES:

STAGE 1: PUMPED 500 SACKS OF CLASS "C" NEAT CEMENT AT  
1200 #; PUMPED PLUG AT 2500 #.

STAGE 2: OPENED DV TOOL AT 2188 FEET AND CIRCULATED THROUGH  
DV TOOL FOR 2 HOURS. PUMPED 700 SACKS OF CLASS "C"  
NEAT CEMENT AT 950 #; PUMPED PLUG AT 2500 #. MAINTAINED  
400 # SHUT IN FOR 10.5 HOURS. RELEASED PRESSURE  
AT 1700 HRS. ON 3/20/82.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]TITLE PRESIDENTDATE 3/22/82APPROVED BY [Signature]TITLE LOGISTDATE 3-22-82