

Mr. Carl Ulvog  
February 17, 1976  
Page - 2

In your letter of December 2, 1975, you state that on September 19, 1975 you visited location, but several pieces of equipment were still on location. Again, on October 1 and November 6, you again visited location and found the pits partially covered and ratty and trashy. I have found this to be true. In previous conversations with you, I related that a man had been paid to do this work. I have found that Mr. Harold Mitchell, 417 North Montgomery, Gilmer, Texas was working for Olympic at that time and was the man who paid for the work. I talked to Mr. Mitchell by phone and he relates this to me. He paid a Mr. George O. Bain, who lives at Logan New Mexico. I talked with Mr. Bain on February 16, 1976 and he agreed that he had been paid for the work. However, equipment was left on the location for quite awhile, and when he was able to get to the location to do the work, he agreed ruts were left and so forth, but said he was afraid to stir up and smooth too much for fear the sand would all blow away. However, he will return to clear location according to your specifications at my request. I will have to pay an additional fee for this work. I would like to know just how this location should be cleared, etc.

I hope the enclosed information is sufficient to fill in that which was lacking in previous reports. I certainly want to cooperate to the fullest in order to provide the Oil Conservation Commission with proper reports and information.

Sincerely,

  
STANLEY J. PIRTLE

SJP/jlc  
Encl: information from Olympic