## STATE OF NEW MEXICO ENERGY MID MINERALS DEPARTMENT

	•	
DISTRIBUTION	1	
SANTA FE		
FILE	17	_
U.3.G.S.	1	
LAND OFFICE		
OPERATOR	1	

## OIL CONSERVATION DIVISION

SANTA FE	P. O. 80	OX 2088	Form C-103	
716	SANTA FE, NEW MEXICO 87501		Revised 10-1-7	
U.S.G.S.		·	5a. Indicate Type of Lease	
OPERATOR			State Fee X	
			5. State Oil & Gas Lease No.	
SUNDRY NO	TICES AND REPORTS ON	WELLS	minimin	
USE "APPLICATION FO	B TO DRILL OR TO DEEPEN OR PLUG R PERMIT -" IFORM C-1011 FOR SU	SACE TO A DIFFERENT RESERVOIR. CH PROPOSALS.)		
#it. □ #ft. ☑	ruen. Carbon Dioxide		7. Unit Agreement Name	
Name of Operator			8. Form or Lease Irane	
Address of Operator	ERIGAS, INC., Carbon Dioxide Division		Mitchell	
4455 LBJ Freeway, Suite 1	100, Dallas, Texas	7523/	9. Well No.	
rocation of well			18	
MAIT LETTER C 660	C 660 North 1980		10. Field and Pool, or Wildcar Mitchell	
THE West	8 TOWNSHIP 18 N	30 E		
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
	GL -		Harding	
Check Appro NOTICE OF INTEN	priate Box To Indicate N	ature of Notice, Report or	Other Data	
MOTICE OF INTEN	TON TO:	SUBSEQU	ENT REPORT OF:	
FORM REMEDIAL WORK	PLUE AND ABANDON	REMEDIAL WORK		
PORARILY ASAMOON		COMMENCE DRILLING OPHS.	ALTERING CASING	
T ON ALTER EASING	CHANGE PLANS	CASING TEST AND CEMENT JOS	PLUS AND ABANDONMENT	
THEA		OTHER Repair casing a	and tubing leaks	
	U			
escribe Proposed or Completed Operations work) SEE RULE 1703.	(Clearly state all pertinent detail	is, and give persinent dates, inclu-	ding estimated date of starting any proposed	
lom marilia di san			sing estimated date of starting any proposed	
Ran packer and tubing to 9 + 1/2" 11.6# flush joint K	91' and attempted to	test casing. Could	not get tested Ron	
1/2" ll.6# flush joint K cement. Circulated 25 s	-55 casing and set a	t 1906' and cemented	with 65 sacks of Class	
C cement. Circulated 25 solug. Lost all pressure a	acks to the pit. 5	1/2" casing split 1/2	bbls. from bumping	
olug. Lost all pressure a second joint. Shut in and	nd returns. Top joi	nt of 4 1/2" casing p	opped out of box on	
second joint. Shut in and Attempted to back off seco	woc. Attempted to	screw casing together	and could not.	
Attempted to back off seco sacks of Class C cement wi	th 2% CoCI Hall 36	ot. Squeezed top of	4 1/2" casing with 15	
sacks behind 4 1/2" casing	and MOC 49 has a	oπ squeeze pressure a	fter displacing 10	
queezed job to 600# 15 m	inutes Test 10 K	illed out to the top	of the 4 1/2" and test	
an internally coated Guib	erson FR-6 pooles	created out to top	of 4 1/2" float collar.	
Packer set at 1845' and had	rkeide was landed :	4 2 3/0 4./# J=33 in	ternally coated tubing.	
acker set at 1845' and backer and casing to 600#	for 15 minutes Too	tn innibited packer f	luid. Tested tubing	
-	manaces, les	ted O.K. Placed well	in production.	
	• .			
eraby comity that the late				
ereby certify that the information above is	rue and complete to the best of m	y knowledge and belief.		
K. M. Suchel _	D -	1 Pin. A		
The state of the s	THE DEGION	al Traduction Thene	ger DATE 11-12-84	
	5	NOTIFIED TO SEE THE STREET OF THE SEE		