Submit 3 Copies	State of New M		Form C-103			
to Appropriate	Energy, Minerals, and Natural Ro	esources Department	Revised 1-1-89			
District Office						
OIL CONSERVATION DIVISION		WELL API NO.				
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-021-20054			
DISTRICT II	RICT II Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease			
P.O. Drawer DD, Artesia, NM 88210		STATE FEE				
DISTRICT III			6. State Oil & Gas Lease No.			
1000 Rio Brazos Rd., Aztec, NM 87410			o. State on & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name			
(FORM C-101) FOR SUCH PROPOSALS.)			" Zouse I value of Clint rigited left I value			
1. Type of Well			BRAVO DOME CO2 GAS UNIT			
OR WELL	GAS WELL OTHER	CO2	3			
2. Name of Operator	wett Uinen		8. Well No.			
AMOCO PRODUCTION COMPANY			2031-181K			
3. Address of Operator			9. Pool name or Wildcat			
P.O. Box 303, AMISTAD, NEW MEXICO 88410			BRAVO DOME CO2 GAS UNIT			
4. Well Location						
Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The WEST Line						
Section 18 Township 20N Range 31E NMPM HARDING County						
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4530 GR_						
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO:    SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	<del></del>					
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X			
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB				
OTHER: OTHER:						
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.						
Set 4-1/2" CIBP @ 1945' with 50' Class C cement on top.						
Circulate well with mud laiden fluid.						
Pressure test 4-1/2" csg to 500 psi. Held.						
Spot 10 sacks of Class C cement @ 1520' - 1369'.						
Spot 5 sacks of Class C cement @ 30' - 3'.						
Cut off wellhead and anchors 3' below ground level						
Cap well with steel plate. Install dry hole marker. Clean location. 11/19/97.						
Odp Well Will Steel plate. Install dry flole flatker. Clean location. 17/19/97.						
Tuesday 1/2/98						
Inspected 1/1/98 OK REJ						
OK KEY						
	$\bigcirc$		] [			
I hereby certify that the information above	is true end complete to the best of my knowledge, and belief.					
SIGNATURE DILLE Trychor TITLE Operations Specialist DATE 10/20/97						
TYPE OR PRINT NAME B. E. Prichard (505) 374-3						
(This space for State Use) DISTRICT SUPERVISOR						
CONDITIONS OF APPROVAL, IF ANY:						
COMPITIONS OF APPROVAL IS AND.	/ /		Surface of All Horat, II ARI. #			