

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-021-20059
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	L 5826
7. Lease Name or Unit Agreement Name	WEST BRAVO DOME CDG UNIT
8. Well No.	2
9. Pool name or Wildcat	WEST BRAVO DOME

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER CO2 SUPPLY WELL	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P. O. Box 840, Seminole, Texas 79360-0840	
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>30</u> Township <u>19N</u> Range <u>30E</u> NMPM <u>HARDING</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4442'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09-17-97 THRU

RU ELDREDGE WELL SVC. KILL WELL W/15 BBLS. 6% KCL. ND TREE & NU BOP. RELEASE PKR. @ 1,872'.
TIH W/10 JTS. 2-3/8" WORKSTRING. TAGGED @ 2,115'. TOH LAYING DOWN PROD. TBG. & PKR. ND
BOP. NU FRAC VALVE. RDMO ELDREDGE WELL SERVICE. MIRU HALLIBURTON WIRELINE SVC. TIH
W/PROTECHNICS RTD BHP GAUGE & SET IN COLLAR STOP @ 1,805'. RDMO HALLIBURTON ON 09-25-97.
MIRU HALLIBURTON FRAC SVC., GUARDIAN WELLHEAD, FLO-CO2 & PROTECHNICS ON 09-26-97. PUMPED FRAC
WITH 71,880# WITH 66,900# OF 12/20 BRADY SAND GOING INTO FORMATION. IMMEDIATELY BEGAN
FLOWBACK. UNLOADING CO2 & WATER WITH 16/64 CHOKE. RD ISOLATION TOOL. NU FLANGE & CONT.'D.
FLOWBACK. RDMO HALLIBURTON. CONNECTED TESTER TO WELL & TST'D. WELL. WELL TST'D. @ 3,336
MCFPD W/420# WELLHEAD PRESS. CI. MIRU HALLIBURTON WIRELINE SVC. TIH W/FISHING TOOL.
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 10/07/97
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 915 758-6773

(This space for State Use)

APPROVED BY Ry Johnson TITLE DISTRICT SUPERVISOR DATE 10/20/97
CONDITIONS OF APPROVAL, IF ANY: