Submit 3 Copies
to Appropriate
District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

| to Appropriate District Office UNIVESTOR | Revised 1-1-89 | | | |
|---|--|--|--|--|
| DISTRICTI OF CONSERVATION DIVISION | WELL API NO. | | | |
| P.O. Box 1980, Hobbs, NM 88240 RE P.O. Box 2088 | 30-021-20060 | | | |
| DISTRICT II P.O. Drawer DD, Artesia, NM, 882101 311 PLOS BARRIE 12, New Mexico 87504-2088 | 5. Indicate Type of Lease STATE FEE | | | |
| DISTRICT III 1000 Rio Brizzos Rd., Aziec, NM 87410 | 6. State Oil & Gas Lease No. | | | |
| SUNDRY NOTICES AND REPORTS ON WELLS | | | | |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" - (FORM C-101) FOR SUCH PROPOSALS.) | 7. Lease Name or Unit Agreement Name Bravo Dome Carbon Dioxio Gas Unit | | | |
| 1. Type of Well: OIL OAS WELL WELL OTHER (C) | | | | |
| 2. Name of Operator | 8. Well No. | | | |
| Amoco Production Company | 9. Pool name or Wildcat Brave Deme | | | |
| 3. Address of Operator P.O. Box 3092 Houston, Texas 77253 | Carbon Dioxide Gas Unit | | | |
| 4. Well Location Unit Letter K: 1950 Feet From The South Line and 195 | C Feet From The West Line | | | |
| | NMPM Harding County | | | |
| Section 17 Township T20N Range R32E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | VIIIIIIIIII | | | |
| ////////////////////////////////////// | Panest or Other Data | | | |
| Check Appropriate Box to Indicate Nature of Notice, F NOTICE OF INTENTION TO: SUI | BSEQUENT REPORT OF: | | | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING | | | |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN | IG OPNS. DPLUG AND ABANDONMENT | | | |
| PULL OR ALTER CASING CASING TEST AND C | CEMENT JOB . | | | |
| OTHER: OTHER: | | | | |
| 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc. work) SEE RULE 1103. | luding estimated date of starting any proposed | | | |
| WORK) SEE RULE 1103. 4/24/92-TPC 335 psi, CPC 300 psi | 1-1 11- SCUPSI OK. | | | |
| · a 2/1 Ctanding value to 1/3 ? | 154 409 5 6 7 6 7 6 6 | | | |
| 5/5/92 - Diopped 2-18 Standing voluced water - 1 Lead Annulus w/ 32 BBL Produced water - 1 | Affermpt to PIS TS | | | |
| $I \in IOOPS() O$ | ニングライ チムベンス おおいこ た | | | |
| | | | | |
| Propose 1 | 1 Lake in well head | | | |
| Cast iron bridge plug + set & 21751, P. it OK, Cap CIBP w/ 25 ft eint, Land 1, | if of you have | | | |
| 1 UK, COP 02- | | | | |
| + movitor annually | | | | |
| I hereby certify that the information above is true and cochiplete to the best of my knowledge and belief. Fills for | reman DATE 5/6/92 | | | |
| TYPE OR PRINT NAME BILLY E. Prichard TITLE Field For | 5053743053 | | | |
| TYPE OR PRINT NAME DILLY E. Frich 2rd | TELEPHONE NO. | | | |
| (This space for State Use) | | | | |
| CONDITIONS OF AFTROVAL F ANY: Key Johnson | Bupinosar DATE 5/6/92 | | | |
| CONDITIONS OF AFFROVAL, IF ANY: Key Johnson | | | | |

| SUNDRY NOTICES AND REPORTS ON WELLS (DOI NOT USE THIS FORM FOR PROPOSALS TO DRILL OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR | Well API No. 30-021-20060 |
|---|--|
| SUNDRE NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF PLUG BACK TO A DIFFERENT RESERVOIR. USE | |
| SUCH PROPOSALS) | 5. Indicate Type of Lease state Fee 6. State Oil & Gas Lease # |
| 1. Type of Well OIL WELL GAS WELL OTHER X CO2 | 7. Lease Name or Unit Agreement Name Bravo Dome CO2 Gas Unit |
| 2. Name of Operator: Amoco Production Company | 8. Well No. 2032-171K |
| 3. Address of Operator: P. O. Box 3092 Houston, TX 77253 | 9. Pool Name or Wildcat Bravo Dome CO2 Gas Unit |
| 4. Well Location Unit Letter K: 1980 Feet From The Soft From the West Line. Section 17 Township 20 Range 32 NMP | outh Line and 1980 Feet M |
| 10. Elevation (Show whether DR, DKB, RT, GR, e | tc.) 4791.6 |
| Plug and Abandon Alter Casing Change Plans Plug and Aban | orary Abandonment |
| pertinent dates, including estimated date | |
| work) SEE RULE 1103. | |
| Move in service unit 5/11/92. Kill well we standing valve. Nipple up BOP. Pull tubin set cast iron bridge plug at 2175 ft. Pres 30 minutes. Okay. Cap CIBP with cement. down BOP. Nipple up wellhead. Move out so Monitor annually. | ng and packer. Run and ssure test CIBP at 500 psi PBTD 2152 ft. Nipple |
| Move in service unit 5/11/92. Kill well we standing valve. Nipple up BOP. Pull tubin set cast iron bridge plug at 2175 ft. Pres 30 minutes. Okay. Cap CIBP with cement. down BOP. Nipple up wellhead. Move out se Monitor annually. I hereby certify that the information above is best of my knowledge and belief. | ng and packer. Run and ssure test CIBP at 500 psi PBTD 2152 ft. Nipple ervice unit 5/12/92. |
| Move in service unit 5/11/92. Kill well we standing valve. Nipple up BOP. Pull tubin set cast iron bridge plug at 2175 ft. Pres 30 minutes. Okay. Cap CIBP with cement. down BOP. Nipple up wellhead. Move out so Monitor annually. I hereby certify that the information above is | ng and packer. Run and soure test CIBP at 500 psi PBTD 2152 ft. Nipple ervice unit 5/12/92. Strue and complete to the Field Foreman Date 6/15/5 |
| Move in service unit 5/11/92. Kill well we standing valve. Nipple up BOP. Pull tubin set cast iron bridge plug at 2175 ft. Pres 30 minutes. Okay. Cap CIBP with cement. down BOP. Nipple up wellhead. Move out so Monitor annually. I hereby certify that the information above is best of my knowledge and belief. Signature Buly 2. Trucker. Title: | ng and packer. Run and soure test CIBP at 500 psi PBTD 2152 ft. Nipple ervice unit 5/12/92. Strue and complete to the Field Foreman Date 6/15/5 |

SME TO SELECT BEST

Table 18 of the Control Mend to

| | • • • • • • • • • • • • • • • • • • • | | | | | • | to approximately the second | |
|----|--|------------|--|-------------------------------|-------|--|-----------------------------|---------------------------------------|
| | Section 1. Section 1 | 4 4 5 | . 2 | 4.0 | | | | •• |
| 1. | 7 184 - 073 | | | Section 1995 | | _ i | £1 | |
| | Queen Gray (ar.) | | | 1.11 821 | | | | |
| 1 | | T. Moura - | | isa Grenabina | | | Graces June 22 | |
| | rasa kalendari da sa | T. Or Sus. | | 7 C1 1505 ± | | 41 | Falt of Same to the con- | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | | | | 4.5 | | 1 | Spy indica | • |
| | | Τ | manager of the same of the sam | | | | Pubb Francisco | |
| | ura — — — — — — — — — — — — — — — — — — — | Τ | | Pera (At) | | -· · · · · · · · · · · · · · · · · · · | | |
| | and the second second | to . | GIL OR OFF | 7 05 0 8 € 3 5 feet | ` (ES | | Pr. | |
| | | | | | | | | |
| | | | | | | | | |

and the second of garan da kanan da ka

| and the second second | and the second |) | | , if the |
|---|----------------|----|---------------------------------------|---------------|
| | | | And the od in Land she | |
| | | | | |
| 51 10 87 | | ·. | 1 105 | filter from A |
| * | | • | | .a) e: |
| | | | · · · · · · · · · · · · · · · · · · · | |