

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER- C02	7. Unit Name Bravo Dome Carbon Dioxide Gas Unit
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name Bravo Dome Carbon Dioxide Gas Unit
3. Address of Operator P.O. BOX 68, HOBBS, NEW MEXICO 88240	9. Well No. 2033-091G
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 20-N RANGE 33-E N.M.P.M.	10. Field and Pool Name Bravo Dome Carbon Dioxide Gas Unit 640-Acre Area

15. Elevation (Show whether DF, RT, GR, etc.)

5070' GL

12. County

Harding

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER Perforate and Stimulate ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to: MISL and kill well w/ 2% KCL FW. Rel pkr, tag PBTD, and POH w/ tbg and pkr. RTH w/ bit and CO to PBTD if necessary. RTH w/ 3 1/8" csg gun and perf the following intervals w/ 2 JSPP and 90° phasing: 2500'-10', 2512'-19', 2527'-44', 2558'-90', 2597'-2616'. RTH w/ pkr, SN, +2 3/8" tbg. Set pkr at 2447'. Pump annular volume of 2% KCL inhibited water down backside. Swab well to kick off flowing. Stimulate w/ 25 tons liquid CO2 as follows: 1) Pump 6 tons as cool down, 2) Pump 15 tons liquid CO2, dropping 4

0+2-NMOCD,SF 1-J.R. Barnett HOU. Rm.21.156 1-F.J. Nash HOU. Rm.4.206 1-WF,Clayton 1-Susp 1-CMH 1-Amerada Hess 1-Amerigas 1-Cities Service 1-Conoco 1-CO2 in Action 1-Sun 1-Excelsior 1-Tex 1-Exxon 1-WF,Hobbs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Wm. L. Fater*

TITLE Admin. Analyst

DATE 10 July 1985

APPROVED BY *Roy Johnson*
CONDITIONS OF APPROVAL, IF ANY:

TITLE DISTRICT SUPERVISOR

DATE 7/4/85

ball sealers per bbl CO₂. Flush w/ 4 tons liquid CO₂.

Flow test well overnight. Return well to production and monitor.