

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-021-20149

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

8. Well No.

2130-021G

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL
WELL ☐

GAS
WELL ☐

OTHER

CO2

2. Name of Operator

AMOCO PRODUCTION COMPANY

3. Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

4. Well Location

Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line
Section 2 Township 21N Range 30E NMPM Harding County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
5294 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations

SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

7/4/00

MIRUSU, kill well with fresh water, NUBOP, release production packer, pull and lay down production tubing and packer, run CIBP on wireline and set at 2,524', run workstring and tag CIBP at 2,524', displace casing with corrosion inhibited fluid, pressure test casing to 500 psi, ok, spot 10 sacks of class C cement from 2524' - 2428', pull workstring to 2115 feet, spot 15 sacks of cement from 2115' - 1971', pull workstring to 30 feet, fill casing with cement, NDBOP, RDMOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.

7/10/00
OK REF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Danny J. Holcomb TITLE Field Foreman

DATE 07-07-2000

TYPE OR PRINT NAME Danny J. Holcomb

TELEPHONE NO. (505) 374-3010

(This space for State Use)

APPROVED BY [Signature]

TITLE

DISTRICT SUPERVISOR

DATE

7/13/00

CONDITIONS OF APPROVAL, IF ANY: