CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION	WELL API NO.
P.O.BOX 2088	30-021-20149
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
CHAIDDY MOTICES AND DEPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name BRAVO DOME CO2 GAS UNIT
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well	
OIL GAS WELL OTHER CO2	
2. Name of Operator	8. Well No.
Amoco Production Company 3. Address of operator	2130-021G
P.O. Box 606 CLAYTON NEW MEXICO 88415	9. Pool name or Wildcat BRAVO DOME CO2 GAS UNIT
4. Well Location	BRAVO DONIE COZ GAS CIVIT
	650 Feet From The EAST Lin
Section 2 Township 21N Range 30E	NMPM HARDING County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
5294 GR	
11. Check Appropriate Box to Indicate Nature of Notice, R	leport, or Other Data
	•
MOTION OF HATELATION TO.	JBSEQUENT REPORT OF:
	JBSEQUENT REPORT OF:
	JBSEQUENT REPORT OF:  ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	ALTERING CASING OPNS. PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE	ALTERING CASING OPNS. PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER: YEAR  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER:	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER: VEAF  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  CASING TEST AND CE  OTHER: YEAR  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER: VEAF  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  CASING TEST AND CE  OTHER: YEAR  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING  CASING TEST AND CE  OTHER:  OTHER:  YEAF  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995  1996	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING  CASING TEST AND CE  OTHER:  OTHER:  YEAF  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER: OTHER: OTHER: YEAF  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995  1996  1997	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER: OTHER: OTHER: YEAF  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995  1996  1997  1998	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  CASING TEST AND CE  OTHER: OTHER: YEAR  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995  1996  1997  1998  1999	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  CASING TEST AND CE  OTHER: OTHER: YEAR  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995  1996  1997  1998  1999	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER: YEAF  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994 1995 1996 1997 1998 1999 2000	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  CASING TEST AND CE  OTHER: OTHER: YEAR  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994  1995  1996  1997  1998  1999	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  PULL OR ALTER CASING CASING TEST AND CE  OTHER: YEAR  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 SEPT. 26 330# 0  1991 SEPT. 23 325# 0  1992 SEPT. 17 325# 0  1993 JUNE 9 325# 0  1994 1995  1996  1997  1998  1999  2000  Thereby certify that the information above is true and complete to the best of my knowledge and belief.	ALTERING CASING OPNS. PLUG AND ABANDONMENT EMENT JOB RLY BRADENHEAD TEST (TA WELL)
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CENTRE:    OTHER: OTHER: YEAR	ALTERING CASING  OPNS. PLUG AND ABANDONMENT  EMENT JOB  RLY BRADENHEAD TEST (TA WELL)  including estimated date of starting any proposed  TECH.  DATE
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CENTRER:    OTHER: OTHER: YEAR	ALTERING CASING  OPNS. PLUG AND ABANDONMENT  EMENT JOB  RLY BRADENHEAD TEST (TA WELL)  including estimated date of starting any proposed