

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals, and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

**WELL API NO.**

30-021-20180

**5. Indicate Type of Lease**

STATE ☒

FEE ☐

**6. State Oil & Gas Lease No.**

L-5890

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"

(FORM C-101) FOR SUCH PROPOSALS.)

**1. Type of Well**

OIL WELL ☐

GAS  
WELL ☐

OTHER

CO2

**2. Name of Operator**

AMOCO PRODUCTION COMPANY

**3. Address of Operator**

P.O. Box 303, AMISTAD, NEW MEXICO 88410

**4. Well Location**

Unit Letter G : 1813 Feet From The NORTH Line and 1650 Feet From The EAST Line  
Section 15 Township 18N Range 33E NMPM HARDING County

**10. Elevation (Show whether DF, RKB, RT, GR, etc.)**

4740 GL

**11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

**12. Describe Proposed or Completed Operations**

SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

4/15/98

Move in rig up service unit and reverse unit. Kill well with fresh water. Nipple up BOP. Pull and lay down 3-1/2" production tubing and packer. Shut in overnight.

4/20/98

Run 2-3/8" workstring to 2480'. Spot 35 sacks of class c cement @ 2480'. Wait on cement. Tag top of cement @ 2370'. Circulate well with mud laden fluid with inhibitor. Pressure test 7" casing to 500 psi. Spot 25 sacks of class c cement @ 2015' - 1870'. Spot 5 sacks class c cement @ 30'-3'. Cut off wellhead and anchors 3' below ground level. Cap with steel plate. Install dry hole marker. Rig down move out service unit. Clean and level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D. J. Holcomb TITLE Field Foreman

DATE 8/17/98

TYPE OR PRINT NAME D. J. Holcomb

TELEPHONE NO. (505) 374-3010

(This space for State Use)

APPROVED BY R. E. Johnson TITLE DISTRICT SUPERVISOR

DATE 8/27/98

CONDITIONS OF APPROVAL, IF ANY: