Submit 3 Copies	State of New M		Form C-103
to Appropriate	Energy, Minerals, and Natural Re	esources Department	Revised 1-1-89
District Office			
<u>DISTRICT I</u>	OIL CONSERVATION DIVISION		WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-021-20186
DISTRICT II P.O. Drawer DD, Artesia, NM 8821	Santa Fe, New Mexico 87504-2088  Artesia, NM 88210		5. Indicate Type of Lease STATE FEE X
DISTRICT III			
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 8	<b>74</b> 10		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
	(FORM C-101) FOR SUCH PROPOSALS.)		Ç
1. Type of Well			BRAVO DOME CO2 GAS UNIT
ON WELL	GAS WELL OTHER	CO2	
2. Name of Operator	WELL OTHER	002	O W H N
AMOCO PRODUCTION	COMPANY		8. Well No. 1833-011G
3. Address of Operator			9. Pool name or Wildcat
P.O. Box 303, AMIS	TAD, NEW MEXICO 88410		BRAVO DOME CO2 GAS UNIT
4. Well Location			
Unit Letter G	: 1650 Feet From The NORTH	Line and1650	Feet From The EAST Line
Section 1	Township 18N	Range 33E NMF	PM HARDING County
	10. Elevation (Show whe 4815	ther DF, RKB, RT, GR, etc.) GL	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO			
NUTICE	OF INTENTION TO:	SUBSEQU	JENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations  (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.			
5/11/98			
Move in rig up service unit. Kill well with fresh water. Nipple up BOP. Pull and lay down 2-3/8" production tbg and packer. Spot 35 sacks class c cement @ 2511'. No tag. Re-spot 25 sacks class c cement @ 2511'. Wait on cement. 5/12/98			
Tag top of cement @ 2368'. Circulate mud laiden fluid with inhibitor. Pressure test 7" to 500 psi. Spot 20 sacks of class c cement @ 2015' - 1895'. Spot 5 sacks class c cement @ 30' - 3'. Cut off wellhead and anchors 3' below ground level. Cap well with steel plate. Install dry hole marker. Rig down, move out service unit. Clean and level location			
DKS-4-98 I hereby certify that the information above is true and copaplete to the bast of my knowledge and belief.			
SIGNATURE	Plantia U-		
TYPE OR PRINT NAME D. J. Ho		ield Team Leader	DATE5/15/88
TELEPHONE NO. (505) 374-3010  [This space for State Use]			
APPROVED BY TY CADRILL TITLE DISTRICT SUPERVISOR DATE 8/10/98			
	V		~ .