Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hoobs NM 88241-1980 P.O. Box 2088 30-021-20191 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 NM 19714 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" WEST BRAVO DOME CDG UNIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: WELL | WELL OTHER CO2 SUPPLY WELL 8. Well No. 2. Name of Operator Amerada Hess Corporation 9. Pool name or Wildcat 3. Address of Operator WEST BRAVO DOME P. O. Box 840, Seminole, Texas 79360-0840 4. Well Location **EAST** 2364 NORTH 1786 Feet From The Line Line and Feet From The Unit Letter 29E HARDING 19N **NMPM** County Range Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5395 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING REMEDIAL WORK HG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PULL OR ALTER CASING UCT OTHER: 12. Describe Proposed or Control Official Official (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 09-18-97 THRU 10-02-97 MIRU ELDREDGE WELL SVC. PU 1 JT. OVER WEIGHT & ROTATED 10 TURNS TO RELEASE LATCH. TOH W/1 JT. CAPPED WELL OFF. ND TREE. CHG. OUT RAMS & NU 3,000# BOP. TOH W/86 JTS. 2-7/8" 6.5# TBG., GUIB. LATCH, SEAL NIPPLE & EXTENSION. FOUND JT. W/HOLE & SEVERAL JTS. ON BTM. W/EXTERNAL PITTING. PU & TIH W/RENTAL WORKSTRING, SEAL NIPPLE & EXTENSION. LATCH INTO UNIPACKER X W/10 PTS. DWN. SPACED OUT W/TBG. IN NEUTRAL. NU FRAC STACK TO TOP OF BOP. TST'D. TBG./STACK TO 2,000#. OK. PRESS'D. UP ON CSG. TO 1,000#. ADAPTER FLANGE ON BTM. OF BOP JUMPED OFF WELLHEAD. WAITING ON 8-5/8" CSG. THREAD X 3,000# API FLANGE ADAPTER FR. WEATHERFORD. RDMO ELDREDGE WELL SVC. RU ELDREDGE WELL SVC. AGAIN ON 09-23-97. ND FRAC STACK & BOP. CHG. OUT FLANGE. ND BOP & FRAC STACK. TST'D. TBG. & STACK TO 2,000#. HELD OK. (CONTINUED) I hereby certify that the information above is true and complete/to the best of my knowledge and belief. TITLE SR. STAFF ASSISTANT 10/07/97 DATE SIGNATURE TELEPHONE NO. 915 758-6778 TYPE OR PRINT NAME TERRY (This space for Sum Vise) DISTRICT SUPERVISOR 10/20