Submit 3 Copies	State of New Me		Form C-103	
to Appropriate	Energy, Minerals, and Natural R	lesources Department	Revised 1-1-89	
District Office	istrict Office			
DISTRICT I	OIL CONSERVATION DIVISION		WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-021-20201	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY	NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name	
	(FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well			BRAVO DOME CO2 GAS UNIT	
ON METT	GAS WELL OTHER	C02		
2. Name of Operator			8. Well No.	
AMOCO PRODUCTION COMP	PANY		1833-261K	
Address of Operator			9. Pool name or Wildcat	
P.O. Box 303, AMISTAD,	NEW MEXICO 88410		BRAVO DOME CO2 GAS UNIT	
4 Wall Leastion				
4. Well Location Unit Letter K: 1980 Feet From The South Line and 1980 Feet From The West Line				
Section 26			M Harding County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)				
4730 GL				
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB				
OTHER:				
12. Describe Proposed or Completed Operations  (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.				
8-22-97				
Set 7" cast iron bridge plug @ 2464' with 50' of class C cement. Circulate well with 9.5 gelled brine water. Pressure test				
to 500#. Held.				
8-23-97  Short 20 peoples of place C compant @ 1064! 1848! Short 5 cooks of place C compant @ 20! 2! Cut off wall head and				
Spot 20 sacks of class C cement @ 1964' - 1848'. Spot 5 sacks of class C cement @ 30' - 3'. Cut off well head and anchors 3' below ground level. Weld steel plate on well. Install dry hole marker.				
lancings 5 below ground level. Weld steel plate on well. Install dry note marker.				
†				
1 1				
I hereby certify that the information above to true and complete to the best of my knowledge and belief.				
SIGNATURE	ly E. Prebue MRE	Operations Specialist	DATE 9/9/97	
TYPE OR PRINT NAME Billy E. Prich	d A		TELEPHONE NO. (505) 374-3053	
(This space for State Use)	511/		00-6-	
APPROVED BY TY COMMUNICATION DISTRICT SUPERVISOR DATE 9-25-87				
CONDITIONS OF APPROVAL, IF ANY:				