

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

RECEIVED
91 NOV 21 AM 9 03
INSPECTED
OK 12-5-91

WELL API NO.

30 021 20209

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

CO2

OTHER

2. Name of Operator

Amoco Production Company

3. Address of Operator

P. O. Box 3092; Houston, TX 77253

4. Well Location

Unit Letter J : 2310 Feet From The SOUTH Line and 2310 Feet From The EAST Line

Section 35

Township 21N

Range 29-E

NMPM

HARDING

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit 7-9-91. Tagged cast iron bridge plug at 2212', and spotted 75 sacks of class C cement. Loaded casing with 28 Bbls of water and pumped 14 bbls at 1 bbl per minute at 100 psi. Shut in overnight, waiting on cement. Tagged cement at 1702'. Loaded casing with 42 Bbls of water and pumped 8 bbls at 2 Bbls per minute at 100 psi. Spot 75 sacks of class C cement and shut in overnight. Tagged cement at 1373'. Loaded casing with 26 Bbls and pressure test casing at 500 psi for 30 min and held O.K. Pulled out of hole to 810' and spot 25 sacks from 810' to 640'. Pull up to 76' and spot 10 sacks from 76' to surface. Moved out service unit 7-11-91. Install P&A marker and cleaned location 7-17-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Randolph

TITLE Admin. Analyst

DATE 11-14-91

TYPE OR PRINT NAME

713/
TELEPHONE NO. 556-3216

(This space for State Use)

APPROVED BY [Signature]

TITLE DISTRICT SUPERVISOR

DATE 12-9-91

CONDITIONS OF APPROVAL, IF ANY: