Submit 3 Copies	State of New M		Form C-103
to Appropriate	Energy, Minerals, and Natural R	lesources Department	Revised 1-1-89
District Office			
DISTRICT I	OIL CONSERVATION	ON DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-021-20211
D. LOUIS LOUIS LA	C4- E- N M O	7504 2000	
DISTRICT II	Santa Fe, New Mexico 8	/504-2088	5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 8821	10		STATE FEE
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 8	7410		
SUI	NDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
	(FORM C-101) FOR SUCH PROPOSALS.)		]
1. Type of Well			BRAVO DOME CO2 GAS UNIT
	GAS		
OF AET	WELL OTHER	C02	
2. Name of Operator			8. Well No.
AMOCO PRODUCTION	COMPANY		1931-231G
3. Address of Operator		- <del></del> -	9. Pool name or Wildcat
P.O. Box 303, AMIS	TAD, NEW MEXICO 88410		BRAVO DOME CO2 GAS UNIT
		· · · · · · · · · · · · · · · · · · ·	Same Same Same Same
4. Well Location			
Unit Letter G 1650 Feet From The NORTH Line and 1650 Feet From The EAST Line			
Section 23	Township 19N	Range 31E NMI	PM HARDING County
	10. Elevation (Show who	ether DF, RKB, RT, GR, etc.)	
	4483	GR	
11	Check Appropriate Box to Indicate	Nature of Notice Ren	ort or Other Date
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE (	OF INTENTION TO:	SUBSEQ	UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPODADII V ADAMOON	CHANCE BI AND	COMMENCE DRIVENIC COME	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations  (Clearly state all portinent datas, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.			
11/25/97			
Set 7" CIBP @ 2050'			
Circulate well with mud laiden fluid			
Pressure test well to 500 psi			
11/26/97			
Spot 15 sacks of Class C cement @ 2050'-1960'			
Spot 25 sacks of Class C cement @ 1619'-1469'			
Spot 5 sacks of Class C cement @ 30'-3'			
Cut off wellhead and anchors 3' below ground level			
Weld steel plate on well			
Install dry hole marke	er , ,		
Clean location  Inspected 1/7/88  OK RES			
$\perp$	nspector 1/1/10		
of Pol			
	UKKY		
	$\rho$ $\sigma$ $-$		
I hereby certify that the information also be true and complete to the best of my knowledge and belief.			
SI GNATURE	CC Part	Onerationa Cassi-E-4	
OF STREET STREET	TITLE	Operations Specialist	DATE 12/1/97
TYPE OR PRINT NAME B. E. PF	NCHARD /		TELEPHONE NO. (505) 374-3053
APPROVED BY	Coffee me	DISTRICT SUPERV	150K DATE 1/12/98
///	<u> </u>	· · · ·	
CONDITIONS OF APPROVAL, IF ANY:	1/		