ıbmit 3 Copies		ate of New Mexi		Form C-103		
Appropriate strict Office	Energy, Minerals, and Natural Resources Department		Revised 1-1-89			
ISTRICT I	OIL CONSERVATION DIVISION			WELL API NO.	WELL API NO.	
O. Box 1980, Hobbs, NM 88240		P.O. Box 2088			30-021-20238	
ISTRICT II O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE FEE		
ISTRICT III 00 Rio Brazos Rd., Aztec. NM 874	10			6. State Oil & Gas Lease No.		
	DRY NOTICES AND REP	ORTS ON WEL	īs			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agree	ment Name	
Type of Well	, ,			BRAVO DOME CO2 GAS	UNIT	
OIL WELL	GAS WELL	OTHER CC	02			
Name of Operator	, , , , , , , , , , , , , , , , , , ,			8. Well No.		
AMOCO PRODUCTION COMPANY				2033-201G		
Address of Operator				9. Pool name or Wildcat		
P.O. Box 303, AM	MISTAD, NEW MEXICO	88410		BRAVO DOME CO2 GAS	UNIT	
Well Location			1000			
Unit Letter G	: 1980 Feet From The	North	Line and 1980	Feet From The East	Line	
Section 20 Township 20N Range 33E NMPM Harding County						
10. Elevation (Show whether DF, RKB, RT, GR, etc.)  5037 GR						
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
ERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK				ALTERING CA	SING	
EMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OP	S PLUG AND AB	ANDONMENT	
JLL OR ALTER CASING	Ħ		CASING TEST AND CEMEN	т ЈОВ	•	
THER:			OTHER:			
Describe Proposed or Completed O	Operations (Clearly state)	all pertinent details, au		n estimated date of starting any propose	od work)	
SEE RULE 1103.						
MIRUSU, kill well as necessary, NUBOP, run workstring to 2,518 feet, spot 6 sacks of class C cement, pull workstring, WOC, run workstring, tag cement, cement should be above 2,450 feet, pressure test casing to 500 psi. displace casing with corrosion inhibited fluid, pull workstring to 2,074 feet, spot 7 sacks of cement, pull workstring to 30 feet and fill casing with cement, NDBOP, RDMOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.						
17	above is true and complete to the be			2.20.00		
	Hiliamb	TITLE Fiel	d Foreman	DATE 2-29-00		
	J. Holcomb			TELEPHONE NO.	(505) 374-3010	
his space for State Use) PROVED BY	. Elokum	- TITLE DIS	TRICT SUPER'	1150) DATE 3/9	100	
ONDITIONS OF APPROVAL IF ANY						