

Submit 3 Copies  
Appropriate  
District Office

State of New Mexico  
Energy, Minerals, and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
  
DISTRICT III  
000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-021-20262
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BRAVO DOME CO2 GAS UNIT
8. Well No. 2133-111K
9. Pool name or Wildcat BRAVO DOME CO2 GAS UNIT

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER CO2
Name of Operator AMOCO PRODUCTION COMPANY
Address of Operator P.O. Box 303, AMISTAD, NEW MEXICO 88410
Well Location Unit Letter K : 1924 Feet From The West Line and 1843 Feet From The South Line Section 11 Township 21N Range 33E NMPM Harding County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4904 GL

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103.

9-5-97  
Circulate well with 9.5 gelled brine water. Spot 15 sacks class C cement @ 2474' - 2233'.

9-6-97  
Tag top of cement @ 2233'. Spot 15 sacks class C cement @ 1920' - 1835'. Spot 5 sacks class C cement @ 30' - 3'.  
Cutt off wellhead and anchors 3' below ground level. Cap well with steel plate. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard	TITLE Operations Specialist	DATE 9/9/97
TYPE OR PRINT NAME Billy E. Prichard	TELEPHONE NO. (505) 374-3053	
APPROVED BY [Signature]	TITLE DISTRICT SUPERVISOR	DATE 9-25-97