Submit 3 Copies to Appropriate District Office

## State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department Revised 1-1-89 OIL CONSERVATION DIVISION **DISTRICT I** WELL API NO. P.O. Box 1980, Hobbs, NM 88240 2040 Pacheco St. 30-021-20278 Santa Fe, NM 87505 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: GAS WELL WELL OTHER BUEYEROS COM Name of Operator 8. Well No. AMOCO PRODUCTION COMPANY Address of Operator 9. Pool name or Wildcat 606, CLAYTON NM 88415 WILDCAT-GRANITE PO BOX Well Location Line and 2280 Feet From The EAST Unit Letter J: 2474 Feet From The SOUTH ship 2]N Range 29E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Section 35 Township **NMPM** HARDING County 5427.50' GL Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. MIRT 13. TEST BOP & EQUIP TO 3000 PSI-OK 2. SPUD 20" HOLE AT 9:30 AM 5/5/96 14. DRILL 10 5/8" HOLE FROM 2693' TO 2831' 3. DRILL 20" HOLE FROM 0' TO 725' 15. RUN 8 5/8" K55CSG, CSG SET AT 2831" 4. RUN 16" 75# & 84# K55 CSG , CSG SET AT 721' 16. CMT WITH 290 SKS CLASS C & 200 SKS CLASS H, 5. CMT WITH 920 SKS OF CLASS C CMT & ADD, CIRC CIRC 12 SKS TO PIT 30 SKS TO PIT 17. CUT OFF & NIPPLE UP BOP 6. WOC 24HRS 18. PRESSURE TEST BOP AT 3000 PSI-OK 7. CUT OFF 16" CSG, NIPPLE UP BOP 19. DRILL 7 7/8 " HOLE FROM 2831' TO 5378' 8. PRESSURE TEST WELLHEAD AT 500 PSI-30 MIN-OK 20. RUN 8 5/8" PKR WITH BLANKING PLUG, PSA 2782' 9. DRILL 14 3/4" HOLE FROM 725' TO 2693' 21. PRESSURE TEST PKR AT 500 PSI-OK 10. RUN 11 3/4" 47# K55 CSG, CSG SET AT 2693" 22. LAY DOWN DRILL PIPE 11. CMT WITH 600 SKS OF CLASS C CMT & ADD, CIRC 23. RIG RELEASED 6/12/96 69 SKS TO PIT **24. MORT** 12. WOC & CUT OFF & NIPPLE UP BOP 25. WAIT ON SERVICE UNIT DATE 6/25/96 FIELD FOREMAN

SIGNATURE TYPE OR PRINT NAME PRICHARD

(This space for State Upd

**DISTRICT SUPERVISOR**